




report date: 2024-03-28

General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE
Colour	Silver
Year of manufacture	2012
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2022-06-20
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-01-09
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #13 2024-01-08 13:33

MOT test number 621898972204

Result ✓ Passed

Next expiry date 2025-01-09

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner (5.2.3 (e))

**Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres cracking on side walls and in tread (5.2.3 (d) (ii))

**Advice** Offside Rear Nail in tyre

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner (5.2.3 (e))

MOT #12 2023-01-10 13:27

MOT test number 756937383043

Result ✓ Passed

**Advice** Passenger seat(s) missing at time of test

MOT #11 2021-12-21 10:34

MOT test number 825704381877

Result ✓ Passed

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #10** 2020-12-14 11:38**MOT test number** 269699611711**Result** ✓ Passed**Advice** Front brake pads wearing low**Advice** Both front tyres wearing at edges**MOT #9** 2020-12-14 10:27**MOT test number** 177793525295**Result** ✗ Failed**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Front brake pads wearing low**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Both front tyres wearing at edges**MOT #8** 2019-12-11 09:44**MOT test number** 435183590426**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #7** 2018-12-13 12:35**MOT test number** 813871060992**Result** ✓ Passed

**MOT #6** 2017-12-21 11:54**MOT test number** 916697823065**Result** ✓ Passed**MOT #5** 2016-12-12 10:02**MOT test number** 918067357789**Result** ✓ Passed**Advice** Bonnet stay faulty**MOT #4** 2016-12-12 10:02**MOT test number** 765897215561**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Bonnet stay faulty**MOT #3** 2015-12-10 11:58**MOT test number** 344777906463**Result** ✓ Passed**MOT #2** 2015-01-09 14:38**MOT test number** 515499405039**Result** ✓ Passed**MOT #1** 2015-01-05 15:11**MOT test number** 946225405038**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
9 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	9 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>CV12DFZ</b>
Plate since	2019-09-28
Current registration	<b>CV12DFZ</b>
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-23
Last registration	2024-01-08
Complete history	<a href="#">See info</a>



Registration #1	2012-03-23	18 mi
Registration #2	2015-01-05	23.232 mi
Registration #3	2015-01-09	23.325 mi
Registration #4	2015-12-10	26.867 mi
Registration #5	2016-12-12	29.361 mi
Registration #6	2016-12-12	29.361 mi
Registration #7	2017-12-21	35.442 mi
Registration #8	2018-12-13	40.547 mi
Registration #9	2019-01-01	41.557 mi
Registration #10	2019-01-01	41.557 mi
Registration #11	2019-01-01	41.557 mi
Registration #12	2019-01-01	41.557 mi
Registration #13	2019-01-01	41.557 mi
Registration #14	2019-01-01	41.557 mi
Registration #15	2019-01-01	41.557 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4250870