



General information

Make	FORD
Model	FIESTA ZETEC
Colour	Black
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-03
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	9
Total items failed	6
MOT #14	2023-05-31 06:48
MOT test number	675687818565
Result	✓ Passed
Next expiry date	2024-06-02
MOT #13	2022-05-30 09:40
MOT test number	482963817859
Result	✓ Passed
MOT #12	2021-06-03 09:35
MOT test number	977483574194
Result	✓ Passed
MOT #11	2020-12-09 16:41
MOT test number	470233372346
Result	✓ Passed

**MOT #10** 2020-12-07 10:10**MOT test number** 587383690955**Result** ✗ Failed

- Fail** Other passenger door cannot be opened from outside the vehicle boot lid (6.2.3 (a))
- Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. wrong size (5.2.3 (b))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #9** 2019-05-31 11:58**MOT test number** 753602199338**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-05-30 10:18**MOT test number** 915575599719**Result** ✓ Passed**MOT #7** 2017-06-02 09:27**MOT test number** 277046556945**Result** ✓ Passed**MOT #6** 2016-06-07 11:13**MOT test number** 408177297304**Result** ✓ Passed**MOT #5** 2016-06-07 07:51**MOT test number** 449606623594**Result** ✗ Failed

- Fail** Nearside Stop lamp not working (1.2.1b)

**MOT #4** 2015-06-05 13:00**MOT test number** 397476155175**Result** ✓ Passed**Notice** Nearside rear tyre starting to deteriorate on outer side wall**Notice** Offside rear tyre starting to deteriorate on outer side wall**MOT #3** 2015-06-05 12:24**MOT test number** 885016255189**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Nearside rear tyre starting to deteriorate on outer side wall**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Offside rear tyre starting to deteriorate on outer side wall**MOT #2** 2014-06-05 10:32**MOT test number** 105646654155**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Notice** Both rear tyres perished**MOT #1** 2013-06-05 10:57**MOT test number** 335446253126**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
2 June 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	2 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-03
Last registration	2023-05-31
Complete history	<a href="#">See info</a>



Registration #1	2010-06-03	26 mi
Registration #2	2013-06-05	19.727 mi
Registration #3	2014-06-05	25.622 mi
Registration #4	2015-06-05	31.826 mi
Registration #5	2015-06-05	31.826 mi
Registration #6	2016-06-07	38.167 mi
Registration #7	2016-06-07	38.167 mi
Registration #8	2017-06-02	44.506 mi
Registration #9	2018-06-02	55.557 mi
Registration #10	2019-06-02	55.557 mi
Registration #11	2020-06-02	55.557 mi
Registration #12	2021-06-02	55.557 mi
Registration #13	2022-06-02	55.557 mi
Registration #14	2023-06-02	55.557 mi
Registration #15	2024-06-02	55.557 mi
Registration #16	2025-06-02	55.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1109 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	9E46444
---------------	---------