



Mercedes-Benz




report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | MERCEDES |
| Model | SLK 350 |
| Colour | Red |
| Year of manufacture | 2007 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.5 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 268 BHP |
| Max. torque | 350 Nm at 5.000 rpm |
| Engine capacity | 3.498 cc |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 19.9 mpg |
| Consumption extra urban | 36.2 mpg |
| Consumption combined | 28.0 mpg |
| CO2 emission | 242 g/km |
| CO2 label | L |



**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-10-10 |
| MOT pass rate | 88 % |
| MOT passed | 15 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 2 |

| | |
|-------------------------|---|
| MOT #17 | 2023-10-03 14:40 |
| MOT test number | 887651076941 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-10 |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |

| | |
|------------------------|------------------|
| MOT #16 | 2022-10-11 08:43 |
| MOT test number | 177474979157 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #15 | 2021-10-26 11:29 |
| MOT test number | 343715987014 |
| Result | ✓ Passed |

| | |
|------------------------|---|
| MOT #14 | 2020-11-17 15:56 |
| MOT test number | 194104156412 |
| Result | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

**MOT #13** 2019-09-26 13:44**MOT test number** 141354318035**Result** ✓ Passed**MOT #12** 2018-10-19 11:12**MOT test number** 172672442315**Result** ✓ Passed**MOT #11** 2018-10-12 11:04**MOT test number** 797291219791**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2017-09-04 12:42**MOT test number** 235394724511**Result** ✓ Passed**Advice** Nearside Front tyre has slight wear on the inner edge**MOT #9** 2016-08-31 14:14**MOT test number** 582925720868**Result** ✓ Passed**MOT #8** 2015-09-01 17:52**MOT test number** 399694445432**Result** ✓ Passed

**MOT #7** 2014-09-02 13:55**MOT test number** 235285544251**Result** ✓ Passed**Advice** Front Front wheel bearing has slight play (2.5.A.3c)**Notice** Nearside rear tyre worn on inner edge**MOT #6** 2014-09-01 15:08**MOT test number** 838634644213**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Notice** Nearside rear tyre worn on inner edge**Advice** Front Front wheel bearing has slight play (2.5.A.3c)**MOT #5** 2013-08-13 10:59**MOT test number** 205855423219**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-08-20 14:29**MOT test number** 567953332265**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2011-08-30 14:31**MOT test number** 328282941234**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #2 | 2011-02-23 09:43 |
| MOT test number | 658704851084 |
| Result | ✓ Passed |
| MOT #1 | 2010-02-03 15:10 |
| MOT test number | 341274230048 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
10 October 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 1 |
| MOT expiry date | 10 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | L |
| Single payment (12 months) | £ 675,00,- |
| Single six month payment | £ 371,25,- |
| Total payable by 12 monthly instalments | £ 708,75,- |




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|------------|
| Number of plates | 7 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2007-03-01 |
| Last registration | 2023-10-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-03-01 | 19 mi |
| Registration #2 | 2010-02-03 | 19.408 mi |
| Registration #3 | 2011-02-23 | 24.308 mi |
| Registration #4 | 2011-08-30 | 26.284 mi |
| Registration #5 | 2012-08-20 | 27.769 mi |
| Registration #6 | 2013-08-13 | 29.085 mi |
| Registration #7 | 2014-09-01 | 36.463 mi |
| Registration #8 | 2014-09-02 | 36.463 mi |
| Registration #9 | 2015-09-01 | 43.157 mi |
| Registration #10 | 2016-09-01 | 50.000 mi |
| Registration #11 | 2017-09-01 | 56.843 mi |
| Registration #12 | 2018-09-01 | 63.686 mi |
| Registration #13 | 2019-09-01 | 70.529 mi |
| Registration #14 | 2020-09-01 | 77.372 mi |
| Registration #15 | 2021-09-01 | 84.215 mi |
| Registration #16 | 2022-09-01 | 91.058 mi |
| Registration #17 | 2023-09-01 | 97.901 mi |
| Registration #18 | 2023-10-03 | 98.408 mi |

More info >



Dimensions & weight

| | |
|-------------|---------|
| Width | 1969 mm |
| Height | 1296 mm |
| Length | 4089 mm |
| Wheel base | 2430 mm |
| Kerb weight | 1485 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 27296330596135 |