



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2005
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-13
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-18
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	41
Total items failed	2

MOT #18	2024-01-31 10:34
MOT test number	731373497291
Result	✓ Passed
Next expiry date	2025-02-18
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #17	2023-02-01 13:16
MOT test number	894369664485
Result	✓ Passed

MOT #16	2022-02-16 12:38
MOT test number	327842873684
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge close to limit 2mm (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge close to limit 2mm (5.2.3 (e))

MOT #15	2021-02-08 11:51
MOT test number	677657846303
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #14**

2020-02-19 16:57

**MOT test number**

985363973908

**Result**

✓ Passed

**Advice** Central Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Fuel Pipe/s corroded

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2020-02-11 16:00

**MOT test number**

135007697532

**Result**

✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Rear Sub-frame corroded and seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Central Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Fuel Pipe/s corroded

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12**

2019-02-13 11:33

**MOT test number**

263696736558

**Result**

✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material nearside & offside (1.1.11 (c))**Advice** Fuel Pipe/s corroded**Advice** Rear Coil spring corroded nearside & offside (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**MOT #11**

2018-02-16 14:56

**MOT test number**

848503191702

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin Both sides (inner pads) (3.5.1g)**Advice** Front Front wheel bearing has slight play Both sides. (2.5.A.3c)**Advice** Nearside Rear Fuel Pipe/s corroded**MOT #10**

2016-10-11 14:14

**MOT test number**

110889855944

**Result**

✓ Passed

**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear exhaust mounts slight deteriorated**MOT #9**

2015-07-27 11:29

**MOT test number**

346438605454

**Result**

✓ Passed

**MOT #8** 2014-05-16 10:54**MOT test number** 178576734107**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-05-16 12:56**MOT test number** 866386633115**Result** ✓ Passed**Advice** Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-05-02 08:36**MOT test number** 705163622141**Result** ✓ Passed**MOT #5** 2012-05-01 14:31**MOT test number** 425842622135**Result** ✗ Failed**Fail** Centre Rear Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #4** 2011-05-10 11:29**MOT test number** 756740731123**Result** ✓ Passed**Advice** Centre Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2010-05-13 12:36**MOT test number** 120443130183**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-05-12 12:31**MOT test number** 483412839125**Result** ✓ Passed**MOT #1** 2008-04-22 13:13**MOT test number** 571643818195**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
18 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	18 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>VF05AEW</b>
Plate since	2019-06-29
Current registration	 <b>VF05AEW</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-05-21
Last registration	2024-01-31
Complete history	<a href="#">See info</a>



Registration #1	2005-05-21	16 mi
Registration #2	2008-04-22	15.920 mi
Registration #3	2009-05-12	30.818 mi
Registration #4	2010-05-13	41.551 mi
Registration #5	2011-05-10	51.895 mi
Registration #6	2012-05-01	62.253 mi
Registration #7	2012-05-02	62.254 mi
Registration #8	2013-05-16	72.084 mi
Registration #9	2014-05-16	89.876 mi
Registration #10	2015-07-27	96.961 mi
Registration #11	2016-05-20	101.277 mi
Registration #12	2017-05-20	101.277 mi
Registration #13	2018-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi
Registration #15	2020-05-20	101.277 mi
Registration #16	2021-05-20	101.277 mi
Registration #17	2022-05-20	101.277 mi
Registration #18	2023-05-20	101.277 mi
Registration #19	2024-01-31	101.277 mi
Registration #20	2024-01-31	101.277 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430676175