



SL57WVO

report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #13</b>	2020-12-05 12:47
<b>MOT test number</b>	114701816951
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-12-11
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

<b>MOT #12</b>	2019-11-30 11:18
<b>MOT test number</b>	888351647822
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

<b>MOT #11</b>	2018-12-05 13:37
<b>MOT test number</b>	839179783218
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2017-12-12 17:00
<b>MOT test number</b>	285096024699
<b>Result</b>	✓ Passed
<b>Advice</b>	Brake pipe slightly corroded both rear (3.6.B.2c)
<b>Advice</b>	Brake pipe slightly corroded both front to rear (3.6.B.2c)

**MOT #9** 2017-12-09 10:30**MOT test number** 425322651987**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Brake pipe slightly corroded both rear (3.6.B.2c)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Emissions not tested (7.3.A.1)**Advice** Brake pipe slightly corroded both front to rear (3.6.B.2c)**MOT #8** 2016-12-10 12:11**MOT test number** 920375428510**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2015-12-04 16:38**MOT test number** 377224222245**Result** ✓ Passed

**MOT #6** 2015-12-04 09:55**MOT test number** 231798246499**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #5** 2014-09-23 10:40**MOT test number** 358986964455**Result** ✓ Passed**MOT #4** 2013-09-18 14:57**MOT test number** 307671363266**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Oil leak**MOT #3** 2012-09-10 11:50**MOT test number** 316174252401**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-09-21 13:46**MOT test number** 365704161427**Result** ✓ Passed



MOT #1	2010-09-27 10:17
MOT test number	884650270239
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-09-28
Last registration	2020-12-05
Complete history	<a href="#">See info</a>



Registration #1	2007-09-28	14 mi
Registration #2	2010-09-27	24.091 mi
Registration #3	2011-09-21	29.597 mi
Registration #4	2012-09-10	35.160 mi
Registration #5	2013-09-18	42.234 mi
Registration #6	2014-09-23	53.553 mi
Registration #7	2015-12-04	67.705 mi
Registration #8	2016-09-28	75.277 mi
Registration #9	2017-09-28	85.277 mi
Registration #10	2018-09-28	95.277 mi
Registration #11	2019-09-28	105.277 mi
Registration #12	2020-09-28	115.277 mi
Registration #13	2021-09-28	125.277 mi
Registration #14	2022-09-28	135.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1205 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1177270