





General information

| Make | RENAULT |
|---------------------|----------------------------|
| Model | CAPTUR DYNAMIQUE S NAV TCE |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 113 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 120 BHP |
|-------------------------|---------------------|
| Max. torque | 205 Nm at 2.000 rpm |
| Engine capacity | 1.197 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 51.4 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-06-18 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-05-03 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 17 |
| Total items failed | 0 |

| MOT #4 | 2023-05-02 11:28 |
|------------------|------------------|
| MOT test number | 665058527291 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-03 |

| MOT #3 | | 2022-05-03 13:56 |
|----------|--|------------------|
| MOT test | number | 849337877387 |
| Result | | ✓ Passed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |





| MOT #2 | | 2022-05-03 11:51 |
|----------|---|------------------|
| MOT test | number | 863152610741 |
| Result | | 🗙 Failed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e)) | |
| MAJOR | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii) |) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #1 | | 2021-05-04 08:40 |
|----------|--|------------------|
| MOT test | number | 145954489548 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 August 2024 | ✓ MOT Expires: 3 May 2024 |
|---|------------------------------------|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 3 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 11.111 |
| Average private trade value | 4 10 200 |





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ******** | |
| NUMBER OF TAXABLE | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-03-28 |
| Last registration | 2023-05-02 |
| Complete history | See info |



| Registration #1 | 2018-03-28 | 19 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-05-04 | 17.480 mi |
| Registration #3 | | 11.777 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | T1.777 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 79% |
| Pedestrian | 61% |
| Safety systems | 81% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1778 mm |
| Height | 1566 mm |
| Length | 4122 mm |
| Wheel base | 2606 mm |
| Kerb weight | 1155 kg |
| Max. allowed weight | 1727 kg |
| Additional information | |
| Fuel tank capacity | 45 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | D447889 |