



report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E








Internet history

Entry 1

Date	2022-01-13
Pictures	25
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-06
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	55
Total items failed	15

MOT #21	2023-12-05 16:30
MOT test number	861236014021
Result	✓ Passed
Next expiry date	2024-12-06

MOT #20	2022-12-07 14:21
MOT test number	345769278043

Result	✓ Passed
--------	----------

**Advice** Rear Tyre worn close to legal limit/worn on edge both tyres only 3mm 175/65/15 (5.2.3 (e))

**Advice** Offside Front Play in steering rack inner joint(s)

**Advice** Oil leak, but not excessive under gearbox (8.4.1 (a) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre only 2mm (5.2.3 (e))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))

**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))

**MOT #19** 2022-01-13 12:33**MOT test number** 393015887725**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Sign of new and fresh paint covered all around underneath**MOT #18** 2021-01-18 14:49**MOT test number** 967899852609**Result** ✓ Passed**MOT #17** 2021-01-18 14:49**MOT test number** 587842555555**Result** ✗ Failed**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #16** 2020-01-14 09:20**MOT test number** 207453441905**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake hose has slight corrosion to ferrule nearside and offside (1.1.12 (f) (i))**Advice** Rear Shock absorbers light misting of oil or has limited damping effect nearside and offside (5.3.2 (b))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))**MOT #15** 2019-01-11 15:59**MOT test number** 938526688270**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))



<b>MOT #14</b>	2019-01-11 09:22
<b>MOT test number</b>	797339219646
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Position lamp not working (4.2.1 (a))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #13</b>	2018-01-17 12:08
<b>MOT test number</b>	182354445646
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Shock absorber has a light misting of oil (2.7.3)
<b>Advice</b>	Exhaust has a minor leak of exhaust gases back box (7.1.2)
<b>Advice</b>	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
<b>Advice</b>	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
<b>Advice</b>	Exhaust has a minor leak of exhaust gases back box (7.1.2)
<b>Advice</b>	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #12**

2018-01-16 12:41

**MOT test number**

165992141967

**Result****✗ Failed**

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**Fail** Nearside Rear Direction indicator not working (1.4.A.2c)

**Advice** Exhaust has a minor leak of exhaust gases back box (7.1.2)

**Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**Advice** Exhaust has a minor leak of exhaust gases back box (7.1.2)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11**

2017-01-19 13:38

**MOT test number**

812888319242

**Result****✓ Passed**

**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Nearside Rear minor corrosion on rear coil spring

**Advice** Rear rear exhaust has corrosion on outer skin

**Advice** Oil leak engine area

**Advice** Offside Rear minor corrosion on rear coil spring

**MOT #10**

2017-01-19 12:07

**MOT test number**

220681525159

**Result****✗ Failed****Advice** Offside Rear minor corrosion on rear coil spring**Advice** Oil leak engine area**Advice** Nearside Rear minor corrosion on rear coil spring**Advice** Rear rear exhaust has corrosion on outer skin**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #9**

2016-01-09 13:08

**MOT test number**

879627557646

**Result****✓ Passed****Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8**

2015-12-29 10:42

**MOT test number**

515462089590

**Result****✗ Failed****Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Headlamp insecure (1.7.3)

**MOT #7** 2015-01-05 17:50**MOT test number** 978585205021**Result** ✓ Passed**MOT #6** 2015-01-05 10:45**MOT test number** 306555705080**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-12-21 12:05**MOT test number** 105675053325**Result** ✓ Passed**MOT #4** 2013-01-07 11:55**MOT test number** 128757003089**Result** ✓ Passed**MOT #3** 2013-01-04 12:39**MOT test number** 705744203093**Result** ✗ Failed

- Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



**MOT #2** 2012-03-13 14:23**MOT test number** 519223872070**Result** ✓ Passed**Notice** Wiper scratches on o/s windscreen**Notice** Slight corrosion rear silencer**MOT #1** 2012-03-06 15:07**MOT test number** 906986862079**Result** ✗ Failed**Notice** Slight corrosion rear silencer**Fail** Offside Front Upper Anti-roll bar ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Wiper scratches on o/s windscreen**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
6 December 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	6 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-03-30
Last registration	2023-12-05
Complete history	<a href="#">See info</a>



Registration #1	2009-03-30	13 mi
Registration #2	2012-03-06	26.596 mi
Registration #3	2012-03-13	26.761 mi
Registration #4	2013-01-04	28.187 mi
Registration #5	2013-01-07	28.187 mi
Registration #6	2013-12-21	35.846 mi
Registration #7	2015-01-05	47.238 mi
Registration #8	2015-01-05	47.238 mi
Registration #9	2015-12-29	58.343 mi
Registration #10	2016-01-09	58.545 mi
Registration #11	2017-01-19	67.166 mi
Registration #12	2017-01-19	67.166 mi
Registration #13	2017-01-19	67.166 mi
Registration #14	2017-01-19	67.166 mi
Registration #15	2017-01-19	67.166 mi
Registration #16	2017-01-19	67.166 mi
Registration #17	2017-01-19	67.166 mi
Registration #18	2017-01-19	67.166 mi
Registration #19	2017-01-19	67.166 mi
Registration #20	2017-01-19	67.166 mi
Registration #21	2017-01-19	67.166 mi
Registration #22	2017-01-19	67.166 mi
Registration #23	2017-01-19	67.166 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	9519694