



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 STYLE
Colour	Grey
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 2


Date	2022-08-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-06-28
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-10-23
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	37
Total items failed	1

MOT #122023-10-06 14:13

MOT test number793706501143

Result✓ Passed

Next expiry date2024-10-23

- Advice** Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Offside Front Upper Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
- Advice** Rear exhaust shield insecure corroded rear
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced [under] (6.1.1 (c) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #11**

2023-10-06 09:27

**MOT test number**

232296779678

**Result****✗ Failed**

- Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Offside Front Upper Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced [under] (6.1.1 (c) (i))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Rear exhaust shield insecure corroded rear
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #10**

2022-10-24 14:56

**MOT test number**

920404074259

**Result****✓ Passed****MOT #9**

2021-10-13 10:51

**MOT test number**

957696603119

**Result****✓ Passed**

**MOT #8** 2021-08-19 08:16**MOT test number** 143726997253**Result** ✗ Failed**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #7** 2020-08-11 11:27**MOT test number** 500487405179**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-08-11 08:05**MOT test number** 871079286569**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-06-24 08:46**MOT test number** 205342046705**Result** ✓ Passed**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))

**MOT #4** 2019-06-24 08:46**MOT test number** 138184059748**Result** ✗ Failed**Pass with rectification** Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**MOT #3** 2018-06-21 11:01**MOT test number** 703232974892**Result** ✓ Passed**Advice** Both rear tyres perished**MOT #2** 2017-06-06 14:48**MOT test number** 619868008082**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2016-06-24 11:47**MOT test number** 970432555882**Result** ✓ Passed**Advice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
23 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	23 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-06-27
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2013-06-27	24 mi
Registration #2	2016-06-24	18.721 mi
Registration #3	2017-06-06	27.754 mi
Registration #4	2018-06-21	37.650 mi
Registration #5	2019-06-24	47.480 mi
Registration #6	2019-06-24	47.480 mi
Registration #7	2020-08-11	56.759 mi
Registration #8	2020-08-11	56.759 mi
Registration #9	2021-06-24	66.038 mi
Registration #10	2022-06-24	75.317 mi
Registration #11	2023-06-24	84.596 mi
Registration #12	2024-06-24	93.875 mi
Registration #13	2025-06-24	103.154 mi
Registration #14	2026-06-24	112.433 mi
Registration #15	2027-06-24	121.712 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FADZ542673