





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|----------------|
| Model | ALMERA SE |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 108 mph |
| 0 - 60 mph | 13.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 121 BHP |
|-------------------------|---------------------|
| Max. torque | 128 Nm at 2.800 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 42.8 mpg |



CarCheck.co.uk page 1/12



HF52NLG report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-02

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #20 2020-12-18 14:59 MOT test number 101695310013

Result \(\sqrt{Passed} \)

Next expiry date 2021-12-17

Advice Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19 2020-12-11 15:20

MOT test number 558902808328

Result X Failed

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Exhaust system insecure (6.1.2 (a))

Advice Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MAJOR Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18 2019-05-31 14:53

MOT test number 781125371261

MOT #17 2019-05-31 13:58

MOT test number 208731087161

Result X Failed

MAJOR Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #16 2018-06-13 14:32

MOT test number 398559519886

CarCheck.co.uk page 3/12



MOT #12

HF52NLG

report date: 2024-03-29

2015-05-07 11:13

MOT #15

MOT test number

Result

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #14

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit slight mishaped (4.1.E.1)

MOT #13 2015-05-08 12:13

MOT test number 216178425451

Result ✓ Passed

MOT test number

Result

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail Brakes imbalanced across an axle (3.7.B.5b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #11

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



MOT #4

Result

MOT test number

HF52NLG

report date: 2024-03-29

2009-03-30 13:26

400739789010

✓ Passed

| MOT #10 | 2013-05-23 11:10 |
|---|---------------------------|
| MOT test number | 547033143118 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2012-05-17 13:54 |
| MOT test number | 706678332189 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2011-05-13 14:24 |
| MOT test number | 569203831128 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| | |
| MOT #7 | 2010-06-07 13:28 |
| MOT test number | 783788350171 |
| Result | ✓ Passed |
| MOT #6 | 2010-06-07 12:30 |
| | |
| MOT test number | 722808350117 |
| MOT test number Result | 722808350117 ✓ Passed |
| Result | ✓ Passed |
| | |
| Result | ✓ Passed |
| Result MOT #5 | ✓ Passed 2010-03-12 14:46 |

CarCheck.co.uk page 5/12



Result

HF52NLG

report date: 2024-03-29

× Failed

MOT #3 2007-11-23 16:11

MOT test number 821627027373

Result ✓ Passed

MOT #2 2007-11-23 12:10

MOT test number 113207827317

Advice Nearside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)

Fail Offside Front Headlamp not in good working order adversely affecting beam image (1.2.4a)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Front Headlamp aim too low (1.8)

Fail Offside Front Headlamp aim not tested (1.8.A.1c)

MOT #1 2006-11-10 11:02

MOT test number 553244916377

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Tyne | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



HF52NLG report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

| Owner | history |
|--------|-----------|
| OWITCI | ilistoi y |

| o mici miscory | |
|---|-------------|
| For how long did the current and previous owner(s) have this NISSAN? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



HF52NLG report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2002-09-01 |
| Last registration | 2020-12-18 |
| Complete history | See info |



| Registration #1 | 2002-09-01 | 18 mi |
|------------------|------------|-----------|
| Registration #2 | 2006-11-10 | 29.146 mi |
| Registration #3 | 2007-11-23 | 39.967 mi |
| Registration #4 | 2007-11-23 | 39.967 mi |
| Registration #5 | 2009-03-30 | 49.133 mi |
| Registration #6 | 2010-03-12 | 50.621 mi |
| Registration #7 | 2010-06-07 | 50.908 mi |
| Registration #8 | 2010-06-07 | 28.177 mi |
| Registration #9 | 2011-05-13 | 62.516 mi |
| Registration #10 | 2012-05-17 | 74.029 mi |
| Registration #11 | 2013-05-23 | 84.814 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.70 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 71.777 66 |
| Registration #17 | | 0.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 0.777 es |
| Registration #20 | | 71.777 66 |
| Registration #21 | | 11,777 66 |
| Registration #22 | | 71.777 66 |
| | | |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1706 mm |
|-------------|---------|
| Height | 1448 mm |
| Length | 4184 mm |
| Wheel base | 2535 mm |
| Kerb weight | 1190 kg |

Additional information

| Fuel tank capacity | 60 I |
|---------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number Carcheck.co.uk | 147258 page 12/12 |