




report date: 2024-03-28

General information

Make	VOLVO
Model	V40 D3 R-DESIGN
Colour	Black
Year of manufacture	2015
Top speed	127 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2


Date	2023-11-29
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-08
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	9
Total items failed	4

**MOT #10** 2023-06-09 16:10

**MOT test number** 307791758991

**Result** ✓ Passed

**Next expiry date** 2024-06-11

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9** 2022-05-23 14:28

**MOT test number** 853696415931

**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #8** 2021-06-12 11:08

**MOT test number** 627319052452

**Result** ✓ Passed

**MOT #7** 2021-04-15 11:53

**MOT test number** 197012495084

**Result** ✓ Passed



<b>MOT #6</b>	2021-04-14 11:04
<b>MOT test number</b>	124625904289
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #5</b>	2020-03-18 17:07
<b>MOT test number</b>	632002053913
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2020-03-18 10:16
<b>MOT test number</b>	945886375887
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #3</b>	2019-02-11 12:11
<b>MOT test number</b>	312187666567
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2018-03-08 14:46
<b>MOT test number</b>	526969434031
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



**MOT #1** 2018-02-27 10:15

**MOT test number** 664260219145

**Result** ✗ Failed

**Fail** Front Tyre tread depth below requirements of 1.6mm both (4.1.E.1)

**Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 March 2025

✓  
**MOT**

**Expires:**  
11 June 2024

**Tax status** Valid until 1 March

**Days left** 307

**MOT expiry date** 11 June 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-




**Damage history**

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	EXAMPLE
<b>Category</b>	EXAMPLE
<b>Type</b>	EXAMPLE



**Damage 2**

<b>Date</b>	EXAMPLE
<b>Category</b>	EXAMPLE
<b>Type</b>	EXAMPLE



**Extra VOLVO salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info >**



**Vehicle valuation**

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>KV15JDZ</b>
Plate since	2015-03-28
Current registration	<b>KV15JDZ</b>
Plate since	2015-03-28

More info >



**Finance check**

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-02
Last registration	2023-06-09
Complete history	<a href="#">See info</a>



Registration #1	2015-03-02	26 mi
Registration #2	2018-02-27	33.147 mi
Registration #3	2018-03-08	33.592 mi
Registration #4	2019-02-11	41.645 mi
Registration #5	2020-03-18	48.967 mi
Registration #6	2020-03-18	48.967 mi
Registration #7	2021-04-14	51.178 mi
Registration #8	2022-06-09	51.178 mi
Registration #9	2022-06-09	51.178 mi
Registration #10	2022-06-09	51.178 mi
Registration #11	2022-06-09	51.178 mi
Registration #12	2022-06-09	51.178 mi
Registration #13	2022-06-09	51.178 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1488 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1384920