



**NU6ILHA**

report date: 2024-03-29

General information

Make	MAZDA
Model	3 TS2
Colour	Red
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





## MOT history

MOT expiry date	2024-10-26
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #11	2023-10-25 10:56
MOT test number	875272130410
Result	✓ Passed
Next expiry date	2024-10-26
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
Advice	Offside Rear Nail in tyre central

MOT #10	2022-10-22 08:45
MOT test number	872829250786
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9	2021-10-27 11:01
MOT test number	888066323394
Result	✓ Passed

MOT #8	2020-06-19 15:34
MOT test number	858198494402
Result	✓ Passed

**MOT #7** 2019-06-12 12:34**MOT test number** 569894700390**Result** ✓ Passed**MOT #6** 2018-05-11 09:00**MOT test number** 887164427030**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2017-06-07 13:09**MOT test number** 612207282727**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit cracking - strong advise (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit cracking - strong advise (4.1.E.1)**MOT #4** 2016-09-23 10:46**MOT test number** 640498669848**Result** ✓ Passed**Advice** Slight fluctuation rear brakes**MOT #3** 2015-09-25 13:51**MOT test number** 864425502723**Result** ✓ Passed**MOT #2** 2015-09-25 08:42**MOT test number** 245277474204**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-09-25 10:28
MOT test number	656088364202
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-09-30
Last registration	2023-10-25
Complete history	<a href="#">See info</a>



Registration #1	2011-09-30	10 mi
Registration #2	2014-09-25	13.714 mi
Registration #3	2015-09-25	19.090 mi
Registration #4	2015-09-25	19.090 mi
Registration #5	2016-09-23	25.806 mi
Registration #6	2017-06-07	31.590 mi
Registration #7	2019-09-20	35.277 mi
Registration #8	2019-09-20	35.277 mi
Registration #9	2019-09-20	35.277 mi
Registration #10	2019-09-20	35.277 mi
Registration #11	2019-09-20	35.277 mi
Registration #12	2019-09-20	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1332 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	Z6 938262