



report date: 2024-03-28

General information

Make	BMW
Model	125 428i M SPORT
Colour	Blue
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	241 BHP
Max. torque	350 Nm at 1.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-25
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-25
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #7	2024-02-20 08:53
MOT test number	327214109898
Result	✓ Passed
Next expiry date	2025-02-25
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #6	2023-02-22 09:47
MOT test number	637185474658
Result	✓ Passed
Advice	All four wheels inner all deteriorated

MOT #5	2022-02-23 09:53
MOT test number	859470221046
Result	✓ Passed
Advice	Front Oil leak, but not excessive transmission oil leak (8.4.1 (a) (i))

**MOT #4** 2021-02-26 10:46**MOT test number** 219699175289**Result** ✓ Passed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords cut in outside sidewall. (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2021-02-22 11:51**MOT test number** 664780486999**Result** ✗ Failed

DANGEROUS Nearside Rear Tyre has ply or cords exposed ply exposed. (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Offside Rear Tyre has ply or cords exposed ply exposed. (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords cut in outside sidewall. (5.2.3 (d) (i))

MOT #2 2019-10-16 11:50**MOT test number** 333310590647**Result** ✓ Passed**MOT #1** 2018-11-15 09:47**MOT test number** 426789835527**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 February 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	25 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-11-16
Last registration	2024-02-20
Complete history	See info



Registration #1	2015-11-16	11 mi
Registration #2	2018-11-15	24.129 mi
Registration #3	2019-10-16	28.970 mi
Registration #4	2021-02-22	37.216 mi
Registration #5	2021-02-26	37.226 mi
Registration #6	2022-05-20	38.377 mi
Registration #7	2022-05-20	38.377 mi
Registration #8	2022-05-20	38.377 mi
Registration #9	2022-05-20	38.377 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1825 mm
Height	1384 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1700 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	A1071049