





General information

Make	ABARTH
Model	PUNTO ABARTH
Colour	Black
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G







Internet history

Entry 1

Date

Pictures

2021-07-26

24

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-08-12	
MOT pass rate	71 %	
MOT passed	12	
Failed MOT tests	5	
Total advice items	20	
Total items failed	7	

MOT #17	2022-08-10 09:25
MOT test number	368965877807
Result	✓ Passed
Next expiry date	2023-08-12
Advice Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2021-08-13 12:09
MOT test number	208722333569
Result	✓ Passed
Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))	

MOT #15	2020-11-06 15:23
MOT test number	797252729772
Result	✓ Passed

MOT #14	2020-02-22 09:01
MOT test number	673467121434
Result	✓ Passed



GK09VKV report date: 2024-03-29

MOT #13	2020-02-22 09:01	
MOT test number	896858187709	
Result	🗙 Failed	
Pass with rectification	Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Pass with rectification	Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Pass with rectification	Offside Front Direction indicator incorrect colour (4.4.3 (a))	

MOT #12		2019-02-06 15:04
MOT test	number	475048406772
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2019-02-06 09:20
MOT test	number 382484002669
Result	× Failed
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





525354838
✓ Passed
2-17 11:40
006172714
✓ Passed

MOT #8	2017-02-09 09:31
MOT test number	541781796118
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front coil spring broken (2.4.C.1a)	

MOT #7	2016-02-26 11:54
MOT test number	518091248853
Result	✓ Passed
MOT #6	2015-06-02 11:22
MOT test number	848363855130
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	





MOT #5	2015-06-01 17:28
MOT test number	727302655117
Result	🗙 Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2014-06-25 14:54
MOT test number	339926874199
Result	✓ Passed
Notice Both rear tyres worn to limit	

МОТ #3	2014-06-25 09:41
MOT test number	139926874195
Result	🗙 Failed
NoticeBoth rear tyres worn to limitFailSupplementary Restraint System warning lamp indicates a fault (5.4.2)	

MOT #2	2013-06-18 11:13
MOT test number	627679663110
Result	✓ Passed

MOT #1	2012-06-20 10:47
MOT test number	498302772121
Result	✓ Passed



GK09VKV report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 14 December 2022	X MOT Expired: 12 August 2023
Tax status	Expired at 14 December 2022
Days left	503 days too late
MOT expiry date	12 August 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra ABARTH salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200





Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this ABARTH had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GK09VKV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-01
Last registration	2022-08-10
Complete history	See info



Registration #1	2009-03-01	12 mi
Registration #2	2012-06-20	21.426 mi
Registration #3	2013-06-18	27.315 mi
Registration #4	2014-06-25	36.447 mi
Registration #5	2014-06-25	36.451 mi
Registration #6	2015-06-01	44.324 mi
Registration #7	2015-06-02	44.325 mi
Registration #8	2016-02-26	46.005 mi
Registration #9	2017-02-09	50.317 mi
Registration #10	2017-02-17	50.330 mi
Registration #11		11.117 esi
Registration #12		10.000 est
Registration #13		11.117 mi
Registration #13 Registration #14		10.000 est
		10.000 est 10.000 est 10.000 est
Registration #14		10.000 est 10.000 est 10.000 est 10.000 est
Registration #14 Registration #15		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est
Registration #14 Registration #15 Registration #16		10.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Dimensions & weight

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1348627