



report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI SE
Colour	Black
Year of manufacture	2005
Top speed	125 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	285 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-05
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-11-26
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	30
Total items failed	16

MOT #192023-11-23 12:03

MOT test number704454951485

ResultX Failed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Offside Obligatory mirror insecure (3.3 (b) (ii))
- Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both inner bushes (5.3.4 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #18**

2022-11-23 10:44

MOT test number

975822846629

Result

✓ Passed

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17

2021-11-27 10:19

MOT test number

636649602927

Result

✓ Passed

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2021-11-17 13:08

MOT test number

585546012792

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15

2020-11-16 16:26

MOT test number

358512485021

Result**✓ Passed**

- Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside front and rear (5.3.4 (a) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside rear (5.3.4 (a) (i))
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))
- Advice** Front Lower Shock absorbers has a slightly worn bush offside and nearside (5.3.2 (c))

MOT #14

2019-11-16 12:11

MOT test number

776975700901

Result**✓ Passed**



MOT #13	2018-11-16 11:39
----------------	------------------

MOT test number	811622265920
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2017-11-15 10:03
----------------	------------------

MOT test number	699594540801
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2016-11-14 17:14
----------------	------------------

MOT test number	284409516337
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
---------------	---

MOT #10	2015-11-16 00:00
----------------	------------------

MOT test number	262082201834
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2014-11-13 09:23
---------------	------------------

MOT test number	969687314331
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2013-11-12 10:14
---------------	------------------

MOT test number	916446513313
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2012-12-17 14:39
---------------	------------------

MOT test number	487712852475
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

**MOT #6** 2011-12-15 17:35**MOT test number** 216739841300**Result** ✓ Passed**MOT #5** 2011-12-15 11:31**MOT test number** 927969041326**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2010-11-23 11:22**MOT test number** 461517420404**Result** ✓ Passed**Advice** Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Advise nail in nsr tyre / and side wall cracked**MOT #3** 2009-11-17 16:01**MOT test number** 773361629372**Result** ✓ Passed**Notice** Cut in n/s/f tyre sidewall**MOT #2** 2008-12-02 14:57**MOT test number** 543137238376**Result** ✓ Passed



MOT #1	2008-12-01 14:22
MOT test number	170756638353
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-10-18
Last registration	2023-11-23
Complete history	See info



Registration #1	2005-10-18	7 mi
Registration #2	2008-12-01	45.918 mi
Registration #3	2008-12-02	45.918 mi
Registration #4	2009-11-17	52.950 mi
Registration #5	2010-11-23	60.110 mi
Registration #6	2011-12-15	71.275 mi
Registration #7	2011-12-15	71.280 mi
Registration #8	2012-12-17	84.413 mi
Registration #9	2013-11-12	94.399 mi
Registration #10	2014-11-13	101.467 mi
Registration #11	2015-11-16	108.093 mi
Registration #12	2016-11-16	115.210 mi
Registration #13	2017-11-16	122.327 mi
Registration #14	2018-11-16	129.444 mi
Registration #15	2019-11-16	136.561 mi
Registration #16	2020-11-16	143.678 mi
Registration #17	2021-11-16	150.795 mi
Registration #18	2022-11-16	157.912 mi
Registration #19	2023-11-16	165.029 mi
Registration #20	2024-11-16	172.146 mi
Registration #21	2025-11-16	179.263 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Kerb weight	1390 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	BKE 027327