



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Blue
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-28
Pictures	10
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2022-11-30 12:20
MOT test number	653249412510
Result	✓ Passed
Next expiry date	2023-12-16
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13	2021-11-17 11:13
MOT test number	330511340585
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Exhaust has a minor leak of exhaust gases clamp (6.1.2 (a))

MOT #12	2021-11-17 11:13
MOT test number	855939438336
Result	✗ Failed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Exhaust has a minor leak of exhaust gases clamp (6.1.2 (a))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #11	2020-12-17 12:11
MOT test number	479464452683
Result	✓ Passed

**MOT #10** 2020-12-15 14:13**MOT test number** 865510356430**Result** ✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #9 2016-05-07 10:10**MOT test number** 879511591345**Result** ✓ Passed**MOT #8** 2016-05-07 09:28**MOT test number** 117892925440**Result** ✗ Failed

- Fail** Exhaust has a major leak of exhaust gases front flexi (7.1.2)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #7 2015-05-14 12:51**MOT test number** 486764735196**Result** ✓ Passed

**MOT #6** 2014-05-19 16:09**MOT test number** 966449634137**Result** ✓ Passed**Notice** Both rear tyres perished**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-05-19 10:44**MOT test number** 608409234130**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Both rear tyres perished**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-05-13 14:20**MOT test number** 166883133184**Result** ✓ Passed**Notice** Front pipe flexi deteriorated**Notice** Front lower arm rear bushes starting to split**MOT #3** 2012-05-18 14:32**MOT test number** 137469332136**Result** ✓ Passed**MOT #2** 2011-05-13 10:19**MOT test number** 965463631146**Result** ✓ Passed**Notice** Front tyres getting low inner edge



MOT #1	2010-05-20 16:57
MOT test number	464130540126
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YJ07MJG
Plate since	2024-03-29
Current registration	 YJ07MJG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-08-16
Last registration	2022-11-30
Complete history	See info



Registration #1	2007-08-16	17 mi
Registration #2	2010-05-20	17.139 mi
Registration #3	2011-05-13	28.288 mi
Registration #4	2012-05-18	41.598 mi
Registration #5	2013-05-13	51.838 mi
Registration #6	2014-05-19	62.680 mi
Registration #7	2014-05-19	62.680 mi
Registration #8	2015-05-14	71.145 mi
Registration #9	2016-05-20	80.277 mi
Registration #10	2017-05-20	89.277 mi
Registration #11	2018-05-20	98.277 mi
Registration #12	2019-05-20	107.277 mi
Registration #13	2020-05-20	116.277 mi
Registration #14	2021-05-20	125.277 mi
Registration #15	2022-05-20	134.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 375475