



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D2 ES
Colour	White
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-15
Pictures	34
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-14
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	4
Total items failed	5

MOT #9	2021-08-16 11:37
MOT test number	249284571121
Result	✓ Passed
Next expiry date	2022-08-15

MOT #8	2020-11-17 09:50
MOT test number	233184746620
Result	✓ Passed

MOT #7	2019-11-28 15:47
MOT test number	305439791964
Result	✓ Passed

MOT #6	2018-12-03 17:00
MOT test number	459942858785
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #5** 2018-12-03 13:48**MOT test number** 927281809868**Result** ✗ Failed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Tyre worn close to legal limit/worn on edge all 4 20551017 (5.2.3 (e))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4 2017-10-05 13:06**MOT test number** 906337267494**Result** ✓ Passed**MOT #3** 2017-10-05 10:47**MOT test number** 412541134610**Result** ✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #2 2016-10-07 10:28**MOT test number** 786324820640**Result** ✓ Passed**MOT #1** 2016-05-12 13:49**MOT test number** 842029576849**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 December 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SP13UYK
Plate since	2024-03-28
Current registration	SP13UYK
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-01
Last registration	2021-08-16
Complete history	See info



Registration #1	2013-06-01	11 mi
Registration #2	2016-05-12	16.198 mi
Registration #3	2016-10-07	16.717 mi
Registration #4	2017-10-05	29.194 mi
Registration #5	2017-10-05	29.194 mi
Registration #6	2018-12-03	52.205 mi
Registration #7	2019-05-29	55.277 mi
Registration #8	2019-05-29	55.277 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2021-08-16	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1519 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	2276903
---------------	---------