



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE VVT
Colour	Grey
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	111 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



## MOT history

MOT expiry date	2025-02-23
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	21
Total items failed	15

MOT #19 2024-02-23 13:00

MOT test number 276918791666

Result ✓ Passed

Next expiry date 2025-02-23

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18 2023-02-22 14:55

MOT test number 394825371488

Result ✓ Passed

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2023-02-22 11:01

**MOT test number**

322886627509

**Result**

✗ Failed

**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16**

2022-02-22 12:46

**MOT test number**

369151056404

**Result**

✓ Passed

**MOT #15**

2021-02-24 12:43

**MOT test number**

110041694013

**Result**

✓ Passed

**MOT #14**

2020-01-20 15:23

**MOT test number**

891734088837

**Result**

✓ Passed

**MOT #13**

2019-01-11 16:29

**MOT test number**

346284297582

**Result**

✓ Passed

**Advice** Offside Rear tyre cracking

**MOT #12** 2018-01-12 12:51**MOT test number** 157799629283**Result** ✓ Passed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #11** 2018-01-11 11:14**MOT test number** 167466740973**Result** ✗ Failed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Front Brake pad(s) wearing thin x2 (3.5.1g)**Fail** Front coil spring broken x2 (2.4.C.1a)**MOT #10** 2017-06-06 10:07**MOT test number** 473832094923**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear tyre cracking sidewall**MOT #9** 2017-06-02 13:59**MOT test number** 318103604125**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Indicator switch insecure not working main beam (1.4.A.1)**Fail** Nearside Rear Inner Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear tyre cracking sidewall

**MOT #8** 2016-05-24 12:03**MOT test number** 796519296738**Result** ✓ Passed**MOT #7** 2015-05-21 11:01**MOT test number** 759291445123**Result** ✓ Passed**Notice** Headlamp dipswitch operation poor**Notice** Both front tyres worn outer sides**MOT #6** 2014-05-13 15:12**MOT test number** 636593334174**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Offside & Nearside front tyres worn on edges**MOT #5** 2013-05-09 15:56**MOT test number** 255349523123**Result** ✓ Passed

**MOT #4** 2013-05-08 13:33**MOT test number** 755348623111**Result** ✗ Failed

- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear coil spring incomplete (2.4.C.1a)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #3** 2012-03-30 13:31**MOT test number** 198770492423**Result** ✓ Passed

- Notice** Brake discs worn uneven on inside edges

**MOT #2** 2011-03-28 09:25**MOT test number** 589677481072**Result** ✓ Passed**MOT #1** 2009-12-07 11:20**MOT test number** 783331949328**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
23 February 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	23 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-01-15
Last registration	2024-02-23
Complete history	<a href="#">See info</a>



Registration #1	2007-01-15	20 mi
Registration #2	2009-12-07	17.290 mi
Registration #3	2011-03-28	22.301 mi
Registration #4	2012-03-30	24.656 mi
Registration #5	2013-05-08	27.737 mi
Registration #6	2013-05-09	27.737 mi
Registration #7	2014-05-13	30.203 mi
Registration #8	2015-05-21	33.287 mi
Registration #9	2016-05-24	35.618 mi
Registration #10	2017-06-02	37.363 mi
Registration #11	2017-06-06	37.363 mi
Registration #12	2019-05-20	39.377 mi
Registration #13	2019-05-20	39.377 mi
Registration #14	2019-05-20	39.377 mi
Registration #15	2019-05-20	39.377 mi
Registration #16	2019-05-20	39.377 mi
Registration #17	2019-05-20	39.377 mi
Registration #18	2019-05-20	39.377 mi
Registration #19	2019-05-20	39.377 mi
Registration #20	2019-05-20	39.377 mi
Registration #21	2019-05-20	39.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2025 mm
Height	1496 mm
Length	3986 mm
Wheel base	2575 mm
Kerb weight	1190 kg
Max. allowed weight	1675 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Engine number**

D014869