



Mercedes-Benz

**KM09MPV**

report date: 2024-03-28

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB P/V
Colour	White
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-06-18
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-08-08
Pictures	18
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-02
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	27
Total items failed	10

MOT #15	2023-08-03 10:55
MOT test number	648815644820
Result	✓ Passed
Next expiry date	2024-08-02
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))

MOT #14	2023-07-29 10:41
MOT test number	636836547666
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))

MOT #13	2022-07-27 16:42
MOT test number	424227488193
Result	✓ Passed

**MOT #12** 2022-07-27 15:06**MOT test number** 846486349228**Result** ✗ Failed**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2021-07-31 16:36**MOT test number** 214180125376**Result** ✓ Passed**MOT #10** 2020-11-07 09:23**MOT test number** 277328000593**Result** ✓ Passed**Advice** Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2019-11-12 11:58**MOT test number** 955021640859**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2019-11-07 12:59

**MOT test number**

587176845719

**Result****✗ Failed**

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Rear Lower Rear fog lamp does not emit a steady red light lens damaged (4.5.4 (a))
- Fail** Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

**MOT #7** 2018-11-13 10:59**MOT test number** 500923405868**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Nearside Rear Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #6** 2017-11-07 15:54**MOT test number** 122073417742**Result** ✓ Passed**MOT #5** 2016-09-07 08:20**MOT test number** 370681598090**Result** ✓ Passed**Advice** Front Steering system has slight free play detected at steering wheel both sides (2.2.A.1b)**MOT #4** 2015-08-22 10:16**MOT test number** 567204835299**Result** ✓ Passed**MOT #3** 2014-08-30 12:11**MOT test number** 906142044268**Result** ✓ Passed**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1a)



MOT #2	2013-08-31 09:28
MOT test number	446873743233
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2012-07-16 10:05
MOT test number	996108692138
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
2 August 2024

Tax status		Valid until 1 August
Days left		93
MOT expiry date		2 August 2024
Full MOT history		<a href="#">See MOT history</a>





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>XXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-08
Last registration	2023-08-03
Complete history	<a href="#">See info</a>



Registration #1	2009-06-08	9 mi
Registration #2	2012-07-16	77.526 mi
Registration #3	2013-08-31	89.384 mi
Registration #4	2014-08-30	100.567 mi
Registration #5	2015-08-22	111.137 mi
Registration #6	2016-09-07	122.584 mi
Registration #7	2017-11-07	131.457 mi
Registration #8	2018-11-13	138.125 mi
Registration #9	2019-11-07	143.789 mi
Registration #10	2020-05-20	151.377 mi
Registration #11	2020-05-20	151.377 mi
Registration #12	2020-05-20	151.377 mi
Registration #13	2020-05-20	151.377 mi
Registration #14	2020-05-20	151.377 mi
Registration #15	2020-05-20	151.377 mi
Registration #16	2020-05-20	151.377 mi
Registration #17	2020-05-20	151.377 mi
Registration #18	2020-05-20	151.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1960 mm
Height	3050 mm
Length	6940 mm
Kerb weight	2280 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	64698551773317