



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | CITROEN |
| Model | C2 LX |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 98 mph |
| 0 - 60 mph | 14.4 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 59 BHP |
| Max. torque | 94 Nm at 3.200 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 36.7 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 48.7 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-28 |
| Pictures | 21 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|------------------|
| MOT #20 | 2021-10-27 06:51 |
| MOT test number | 826398348708 |
| Result | ✓ Passed |
| Next expiry date | 2022-10-26 |

| | |
|------------------------|------------------|
| MOT #19 | 2021-01-22 11:24 |
| MOT test number | 852961378698 |
| Result | ✓ Passed |

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

| | |
|------------------------|------------------|
| MOT #18 | 2019-07-24 16:23 |
| MOT test number | 758556573810 |
| Result | ✓ Passed |

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

| | |
|------------------------|------------------|
| MOT #17 | 2019-07-24 16:23 |
| MOT test number | 204193102273 |
| Result | ✗ Failed |

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2018-07-03 07:26**MOT test number** 137694058605**Result** ✓ Passed**Advice** F discs condition**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** O/s/r bump stop condition**MOT #15** 2017-07-26 16:48**MOT test number** 591658269935**Result** ✓ Passed**MOT #14** 2016-09-02 08:28**MOT test number** 811296868391**Result** ✓ Passed**MOT #13** 2016-09-02 07:32**MOT test number** 999064929773**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #12** 2015-08-20 14:51**MOT test number** 763333557237**Result** ✓ Passed

**MOT #11** 2015-08-19 12:03**MOT test number** 787261677515**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #10** 2014-09-12 09:25**MOT test number** 918275854245**Result** ✓ Passed**MOT #9** 2013-09-05 13:54**MOT test number** 329878943407**Result** ✓ Passed**MOT #8** 2013-09-05 09:31**MOT test number** 147828343235**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2012-09-06 14:22**MOT test number** 525940652259**Result** ✓ Passed

**MOT #6** 2012-09-06 10:17**MOT test number** 556070552258**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2011-08-24 08:35**MOT test number** 947086131203**Result** ✓ Passed**Notice** Both rear tyre splitting on sidewalls**MOT #4** 2010-08-31 09:28**MOT test number** 432713140249**Result** ✓ Passed**MOT #3** 2009-08-27 09:14**MOT test number** 654179239204**Result** ✓ Passed**MOT #2** 2008-09-18 11:54**MOT test number** 950582068241**Result** ✓ Passed**Notice** N/s/f tyre low outer edge**MOT #1** 2007-09-12 11:15**MOT test number** 871985857231**Result** ✓ Passed**Notice** Nail in nearside rear tyre



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | EX54KAJ |
| Plate since | 2019-09-28 |
| Current registration | EX54KAJ |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2004-09-20 |
| Last registration | 2021-10-27 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2004-09-20 | 24 mi |
| Registration #2 | 2007-09-12 | 19.948 mi |
| Registration #3 | 2008-09-18 | 28.029 mi |
| Registration #4 | 2009-08-27 | 32.071 mi |
| Registration #5 | 2010-08-31 | 35.908 mi |
| Registration #6 | 2011-08-24 | 40.440 mi |
| Registration #7 | 2012-09-06 | 45.972 mi |
| Registration #8 | 2012-09-06 | 45.972 mi |
| Registration #9 | 2013-09-05 | 50.525 mi |
| Registration #10 | 2013-09-05 | 50.525 mi |
| Registration #11 | 2014-09-12 | 55.280 mi |
| Registration #12 | 2015-09-12 | 55.280 mi |
| Registration #13 | 2016-09-12 | 55.280 mi |
| Registration #14 | 2017-09-12 | 55.280 mi |
| Registration #15 | 2018-09-12 | 55.280 mi |
| Registration #16 | 2019-09-12 | 55.280 mi |
| Registration #17 | 2020-09-12 | 55.280 mi |
| Registration #18 | 2021-09-12 | 55.280 mi |
| Registration #19 | 2022-09-12 | 55.280 mi |
| Registration #20 | 2023-09-12 | 55.280 mi |
| Registration #21 | 2024-03-28 | 55.280 mi |
| Registration #22 | 2024-03-28 | 55.280 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1654 mm |
| Height | 1461 mm |
| Length | 3666 mm |
| Wheel base | 2315 mm |
| Kerb weight | 932 kg |
| Max. allowed weight | 1340 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 41 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | FP7P4568056 |