



BXIIVYP

report date: 2024-03-29

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L





Internet history

Entry 3


Date	2023-11-19
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 2


Date	2023-03-06
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-25
Pictures	26
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-23
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #11 2023-05-24 16:21

MOT test number 549271016212

Result ✓ Passed

Next expiry date 2024-05-23

Advice Nearside Play in steering rack inner joint(s)**Advice** Offside Play in steering rack inner joint(s)

MOT #10 2023-05-19 12:10

MOT test number 713095947537

Result ✗ Failed**Advice** Nearside Play in steering rack inner joint(s)**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Reverse light inop**Fail** Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Offside Play in steering rack inner joint(s)**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil residue

**MOT #9** 2022-09-27 12:47**MOT test number** 300735474124**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-05-12 08:42**MOT test number** 664430482148**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #7** 2020-06-04 09:06**MOT test number** 498991989512**Result** ✓ Passed**MOT #6** 2019-07-20 08:18**MOT test number** 906071001763**Result** ✓ Passed**MOT #5** 2018-07-07 09:25**MOT test number** 610231614840**Result** ✓ Passed**MOT #4** 2017-06-30 11:13**MOT test number** 960150777677**Result** ✓ Passed



MOT #3	2016-07-07 14:06
MOT test number	225879872156
Result	✓ Passed

MOT #2	2015-07-15 11:21
MOT test number	705136495187
Result	✓ Passed

MOT #1	2014-03-26 15:43
MOT test number	978985884011
Result	✓ Passed

- Notice

No emissions report-engine clean
- Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

X

Untaxed

Tax expired:
4 November 2023

✓

MOT

Expires:
23 May 2024

Tax status	Expired at 4 November 2023
Days left	176 days too late
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	BX11VYP
Plate since	2024-03-29
Current registration	BX11VYP
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-31
Last registration	2023-05-24
Complete history	See info



Registration #1	2011-03-31	20 mi
Registration #2	2014-03-26	37.036 mi
Registration #3	2015-07-15	43.052 mi
Registration #4	2016-07-07	47.099 mi
Registration #5	2017-06-30	54.759 mi
Registration #6	2018-07-07	60.358 mi
Registration #7	2019-07-20	66.819 mi
Registration #8	2020-06-04	70.849 mi
Registration #9	2021-05-20	75.277 mi
Registration #10	2022-05-20	79.277 mi
Registration #11	2023-05-24	83.277 mi
Registration #12	2024-03-29	87.277 mi
Registration #13	2025-03-29	91.277 mi
Registration #14	2026-03-29	95.277 mi
Registration #15	2027-03-29	99.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT