





report date: 2024-03-28

General information

Make	FORD	
Model	GALAXY TITANIUM TDCI	
Colour	Silver	
Year of manufacture	2012	
Top speed	124 mph	
0 - 100 km/h	11.1 seconds	
0 - 60 mph	10.4 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



WJ12EVN

report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-08

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date 2021-09-08

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	8
Total items failed	15

MOT #15	2023-10-04 13:02
MOT test number	340608881367
Result	✓ Passed
Next expiry date	2024-10-15
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2023-10-03 13:55
MOT test number	924512389726
Result	X Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #13	2022-10-14 14:11
MOT test number	803251321658
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



WJ12EVN

report date: 2024-03-28

MOT #12 2022-10-11 14:21

MOT test number 708935221229

Result X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Tyre worn close to legal limit/worn on edge Front tyres (5.2.3 (e))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2021-10-16 11:25

MOT test number 688087936405

Result \sqrt{Passed}

MOT #10 2021-03-03 14:27

MOT test number 807909808087

Result \(\sqrt{Passed} \)

MOT #9 2021-03-03 09:46

MOT test number 222956032687

Result X Failed

Fail Rear Direction indicator incorrect colour both (4.4.3 (a))

Fail Stop lamp(s) not working middle (4.3.1 (a) (ii))

Fail Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords both side (5.2.3 (d) (i))

Fail Offside Outer Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

CarCheck.co.uk page 4/13



MOT #8 2021-03-03 09:41

MOT test number 859638143649

Result X Failed

Fail Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords both (5.2.3 (d) (i))

Fail Rear Direction indicator incorrect colour both (4.4.3 (a))

Fail Offside Outer Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Stop lamp(s) not working middle (4.3.1 (a) (ii))

MOT #7 2020-03-07 10:21

MOT test number 429820034552

Result ✓ Passed

MOT #6 2020-03-07 10:21

MOT test number 228646852513

Result X Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #5 2019-03-09 12:59

MOT test number 415892124183

Result Passed

MOT #4 2018-02-10 11:51

MOT test number 579578477436

Result ✓ Passed

MOT #3 2017-03-09 15:42

MOT test number 864049749993

Result ✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/13



 MOT #2
 2016-02-01 12:02

 MOT test number
 751067605713

 Result
 ✓ Passed

 MOT #1
 2015-01-26 10:08

 MOT test number
 298606725049

 Result
 ✓ Passed

 Advice
 Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1 **Date** Category **Type** Damage 2 **Date** Category **Type**



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO. C.	
HEREFE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPERT	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-02
Last registration	2023-10-04
Complete history	See info



Registration #1	2012-03-02	28 mi
Registration #2	2015-01-26	7.626 mi
Registration #3	2016-02-01	21.252 mi
Registration #4	2017-03-09	41.563 mi
Registration #5	2018-02-10	58.399 mi
Registration #6	2019-03-09	64.801 mi
Registration #7	2020-03-07	70.116 mi
Registration #8	2020-03-07	70.116 mi
Registration #9	2021-03-03	72.594 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 esp

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionir
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 13/