



BGI2XNU

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	385 Nm at 1.600 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	34.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-19
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-28
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	37
Total items failed	12

MOT #13	2024-02-29 16:52
MOT test number	348665840927
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (Both arm REAR bush) (5.3.4 (a) (i))

MOT #12	2024-02-29 16:52
MOT test number	479602106203
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (Both arm REAR bush) (5.3.4 (a) (i))
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #11**

2022-09-27 15:34

MOT test number

620083506097

Result

✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH SIDES
REAR BUSHES (5.3.4 (a) (i))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #10

2021-09-29 08:37

MOT test number

358103958253

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner tread (5.2.3 (e))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front wishbones
rear bushes peeling (5.3.4 (a) (i))

MOT #9

2020-10-01 16:16

MOT test number

572822892043

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner tread (5.2.3 (e))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front wishbones
rear bushes peeling (5.3.4 (a) (i))

Advice Nearside Front Nail in tyre

MOT #8

2019-09-25 08:14

MOT test number

466192008848

Result

✓ Passed

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #7**

2018-09-25 14:06

MOT test number

910433331412

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush peeling away (5.3.4 (a) (i))

Advice O/s/f tyre edge wearing

MOT #6

2018-09-24 08:36

MOT test number

371959978637

Result

✗ Failed

Advice O/s/f tyre edge wearing

Fail Fuel cap/sealing device ineffective (6.1.3 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material cross axle (1.1.11 (c))

Fail Stop lamp(s) all not working (4.3.1 (a) (iii))

Fail Nearside Front Position lamp not working (4.2.1 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush peeling away (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a))

MOT #5

2017-09-18 14:06

MOT test number

245467124940

Result

✓ Passed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #4**

2017-09-18 08:30

MOT test number

368789869271

Result**✗ Failed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** N/s wiper blade splitting
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Rear Tyre worn close to the legal limit on 2.5mm limit is 1.6mm (4.1.E.1)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #3

2016-09-09 08:23

MOT test number

911314018796

Result**✓ Passed**

- Advice** Very slight corrosion to n/s/r brake disc inner face
- Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)
- Advice** N/s/f tyre has a superficial cut to outer wall

MOT #2

2016-09-09 08:23

MOT test number

926084229310

Result**✗ Failed**

- Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)
- Advice** Very slight corrosion to n/s/r brake disc inner face
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** N/s/f tyre has a superficial cut to outer wall



MOT #1	2015-09-29 08:39
MOT test number	730626805984
Result	✓ Passed
Advice	N/s/r brake disc corroding on inner face
Advice	N/s/f tyre cut on outer wall (not deep enough to reach cords)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
28 February 2025

Tax status		Valid until 1 March
Days left		307
MOT expiry date		28 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-11
Last registration	2024-02-29
Complete history	See info



Registration #1	2012-06-11	27 mi
Registration #2	2015-09-29	60.204 mi
Registration #3	2016-09-09	68.067 mi
Registration #4	2016-09-09	68.067 mi
Registration #5	2017-09-18	75.992 mi
Registration #6	2017-09-18	75.992 mi
Registration #7	2018-09-24	81.786 mi
Registration #8	2018-09-25	81.786 mi
Registration #9	2019-09-29	88.207 mi
Registration #10	2019-09-29	88.207 mi
Registration #11	2019-09-29	88.207 mi
Registration #12	2019-09-29	88.207 mi
Registration #13	2019-09-29	88.207 mi
Registration #14	2019-09-29	88.207 mi
Registration #15	2019-09-29	88.207 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	CB51893