



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE DCI N-TEC
Colour	Silver
Year of manufacture	2011
Top speed	102 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-06-10
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	38
Total items failed	11

MOT #14 2023-11-09 11:18

MOT test number 144223305873

Result ✓ Passed

Next expiry date 2024-11-10

- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension spring mounting prescribed area is corroded but not considered excessive inner wing (5.3.6 (a) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** General surface corrosion to all underside components/areas
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #13 2022-11-01 17:00

MOT test number 713407426428

Result ✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive chassis leg (5.3.6 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2022-10-29 15:53

MOT test number

177632179012

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive chassis leg (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #11**

2021-11-11 12:06

MOT test number

155559367433

Result**✓ Passed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2020-10-16 12:28

MOT test number

701712903994

Result**✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2020-10-15 11:23**MOT test number** 394794242156**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #8** 2019-10-31 09:18**MOT test number** 265593898049**Result** ✓ Passed**MOT #7** 2018-10-03 13:07**MOT test number** 309304927487**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm in places (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6**

2018-10-03 08:19

MOT test number

788315572183

Result**✗ Failed****Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm in places (5.2.3 (e))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #5**

2017-10-06 09:26

MOT test number

355012962294

Result**✓ Passed****Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4**

2016-10-11 09:09

MOT test number

405460190829

Result**✓ Passed****Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #3** 2016-10-10 09:40**MOT test number** 317721459485**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Fail** Nearside Front Suspension arm has excessive play in a ball joint bottom (2.4.G.2)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Stop lamp not working (1.2.1b)**MOT #2** 2015-09-29 08:26**MOT test number** 681144429382**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #1** 2014-10-06 11:20**MOT test number** 838229974233**Result** ✓ Passed**Notice** Offside wiper smearing



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
10 November 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	KV61HPK
Plate since	2019-09-28
Current registration	KV61HPK
Plate since	2019-09-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-17
Last registration	2023-11-09
Complete history	See info



Registration #1	2011-10-17	10 mi
Registration #2	2014-10-06	35.100 mi
Registration #3	2015-09-29	47.275 mi
Registration #4	2016-10-10	60.392 mi
Registration #5	2016-10-11	60.392 mi
Registration #6	2017-10-06	76.087 mi
Registration #7	2018-10-03	86.998 mi
Registration #8	2018-10-03	86.998 mi
Registration #9	2019-10-03	102.913 mi
Registration #10	2019-10-03	102.913 mi
Registration #11	2019-10-03	102.913 mi
Registration #12	2019-10-03	102.913 mi
Registration #13	2019-10-03	102.913 mi
Registration #14	2019-10-03	102.913 mi
Registration #15	2019-10-03	102.913 mi
Registration #16	2019-10-03	102.913 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1690 mm
Height	1550 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1165 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	016953