





report date: 2024-03-28

### General information

Make	FORD
Model	TRANSIT 350 LWB EF HR DRW P/V 100
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	285 Nm at 1.600 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2021-02-05
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	20
Total items failed	0

MOT #9		2020-02-06 14:05
MOT test	number	266295034072
Result		✓ Passed
Next expi	ry date	2021-02-05
Advice	Front Wheel bearing slightly noisy both (5.1.3 (b) (i))	
<b>Advice</b> sill drivers	Offside Front Inner Seat belt anchorage prescribed area is corroded but step (7.1.1 (a) (i))	ut not considered excessive

MOT #8		2020-01-27 11:52
MOT test	number	657163153289
Result		<b>X</b> Failed
<b>Advice</b> sill drivers	Offside Front Inner Seat belt anchorage prescribed area is corroded but not step $(7.1.1 \ (a) \ (i))$	considered excessive
MAJOR	Hazard warning switch inoperative ignition off (4.4.2 (a) (ii))	
MAJOR	Nearside Rear Direction indicator not working (4.4.1 (a) (ii))	
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Offside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice	Front Wheel bearing slightly noisy both (5.1.3 (b) (i))	
MAJOR	Offside Rear Direction indicator not working (4.4.1 (a) (ii))	
MAJOR	Offside Rear fog lamp not working (4.5.1 (a) (ii))	

CarCheck.co.uk page 2/11



MOT #7 2017-01-06 15:58

**MOT test number** 303541582502

MOT #6 2015-11-07 09:40

**MOT test number** 720921371497

**Result** ✓ Passed

**MOT #5** 2014-11-05 09:51

**MOT test number** 998019104331

Result \( \sqrt{Passed} \)

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Notice** Gearbox leaking oil.

**MOT #4** 2013-09-18 16:49

MOT test number 417161263245

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/11



MOT test number

855324362260

Result

Notice Offside rear hub leaking.

Advice Nearside Inner Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Notice Play in steering rack inner joint(s)

Advice Offside Inner Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

MOT #2	2011-09-14 12:46
MOT test number	365177651272
Result	✓ Passed
MOT #1	2010-09-08 13:58
MOT test number	332111950441
Result	✓ Passed

CarCheck.co.uk page 4/11



#### Tax & MOT check

**Tax status** 





**Tax expired:**9 February 2021
5 Feb

Expired at 9 February 2021

Days left 1174 days too late

MOT expiry date 5 February 2021

Full MOT history See MOT history

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
HARMAN	
*************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2007-09-24
Last registration	2020-02-06
Complete history	See info



Registration #1	2007-09-24	16 mi
Registration #2	2010-09-08	71.635 mi
Registration #3	2011-09-14	91.968 mi
Registration #4	2012-09-20	116.371 mi
Registration #5	2013-09-18	129.369 mi
Registration #6		
Registration #0		
Registration #7		1.77 4
-		11.77 m
Registration #7		1.77 m

More info >

CarCheck.co.uk page 10/11



### Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	2492 mm
Height	2025 mm
Length	6385 mm
Max. allowed weight	3500 kg

## Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	7
Engine number	6A17202

CarCheck.co.uk page 11/11