





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|----------------|
| Model | S-MAX |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 121 mph |
| 0 - 100 km/h | 10.2 seconds |
| Gearbox | 6 speed manual |

Engine & fuel consumption

| Power | 103 kW / 140 HP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 50.0 mpg |
| Consumption combined | 44.4 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-12-05

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2025-03-13 |
|--------------------|------------|
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 2 |

| MOT #13 | | 2024-03-14 09:47 |
|---|--|------------------|
| MOT test i | number | 642909007643 |
| Result | | ✓ Passed |
| Next expir | y date | 2025-03-13 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge Slightly worn on inner edge (5.2.3 (e)) | | |
| Advice | Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (| (i)) |
| Advice Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e)) | | edge (5.2.3 (e)) |
| Advice | Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) | |

| MOT #12 | 2023-09-05 10:42 |
|-----------------|------------------|
| MOT test number | 685538014363 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2023-03-31 13:25 |
| MOT test number | 783309348315 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2022-12-06 11:23 |
| MOT test number | 148849863908 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



MOT #9 2022-12-06 11:23

MOT test number 247869986058

Result X Failed

Pass with rectification

Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Pass with rectification

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #8 2021-12-13 09:01

MOT test number 857779399503

Result ✓ Passed

MOT #7 2021-03-24 10:59

MOT test number 990565084932

Result \rightarrow Passed

MOT #6 2020-05-01 10:48

MOT test number 322054246211

MOT #5 2019-05-28 08:34

MOT test number 750293509857

Result ✓ Passed

MOT #4 2018-05-30 14:13

MOT test number 113556634215

Result ✓ Passed

MOT #3 2017-05-09 09:06

MOT test number 737557632148

Result

Passed

CarCheck.co.uk page 4/12



MOT #2

MOT test number

Result

Advice Nearside rear panel

| MOT #1 | 2015-05-29 10:05 |
|-----------------|------------------|
| MOT test number | 236969345146 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 215 |
| MOT expiry date | 13 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e mier metery | |
|--|-------------|
| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report | |
| | |
| THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR | |
| | |
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2014-09-22 |
| Last registration | 2024-03-14 |
| Complete history | See info |



| Registration #1 | 2014-09-22 | 16 mi |
|------------------|------------|------------|
| Registration #2 | 2015-05-29 | 21.243 mi |
| Registration #3 | 2016-05-06 | 55.979 mi |
| Registration #4 | 2017-05-09 | 94.289 mi |
| Registration #5 | 2018-05-30 | 119.013 mi |
| Registration #6 | 2019-05-28 | 144.048 mi |
| Registration #7 | 2020-05-01 | 154.182 mi |
| Registration #8 | 2021-03-24 | 155.193 mi |
| Registration #9 | | 9.70 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.70 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.177 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.117 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1884 mm |
|-------------|---------|
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1590 kg |

Additional information

| Fuel tank capacity | 70 I |
|--------------------|---------|
| Number of axles | 2 |
| Engine number | EA09685 |

CarCheck.co.uk page 12/12