



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D R-DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-07-19
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-22
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	18
Total items failed	9

MOT #16	2024-03-13 13:56
MOT test number	485942528764
Result	✓ Passed
Next expiry date	2025-03-22

MOT #15	2023-03-10 16:52
MOT test number	988781658943
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2023-03-09 10:58
MOT test number	694478553269
Result	✗ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #13** 2022-03-18 12:00**MOT test number** 643241427520**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2022-03-18 11:08**MOT test number** 786690876144**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Headlamp aim too high (4.1.2 (a))**MOT #11** 2021-03-23 11:19**MOT test number** 169262681423**Result** ✓ Passed**Advice** All direction indicators slightly discoloured Both Rear (4.4.3 (a))**Advice** Both Front Tyre's Worn On Inner & Outer Edges**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #10** 2020-02-07 12:05**MOT test number** 397182934574**Result** ✓ Passed

**MOT #9** 2019-03-01 15:32**MOT test number** 262351573415**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and wearing unevenly on inner edge (5.2.3 (d) (ii))**Minor** Windscreen wiper blade defective both front (3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking and wearing unevenly on inner edge (5.2.3 (d) (ii))**MOT #8** 2018-02-15 10:43**MOT test number** 491208095732**Result** ✓ Passed**MOT #7** 2017-05-03 11:36**MOT test number** 236397687852**Result** ✓ Passed**MOT #6** 2016-05-12 12:08**MOT test number** 928351259404**Result** ✓ Passed**MOT #5** 2016-05-12 09:18**MOT test number** 476807929165**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2015-04-28 11:50**MOT test number** 968538415117**Result** ✓ Passed

**MOT #3** 2015-04-28 11:50**MOT test number** 377508715119**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #2 2014-04-29 09:57**MOT test number** 475339314179**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #1 2013-05-08 16:59**MOT test number** 789908523133**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-17
Last registration	2024-03-13
Complete history	See info



Registration #1	2010-05-17	26 mi
Registration #2	2013-05-08	28.194 mi
Registration #3	2014-04-29	37.863 mi
Registration #4	2015-04-28	45.958 mi
Registration #5	2016-05-12	50.968 mi
Registration #6	2016-05-12	50.968 mi
Registration #7	2017-05-03	52.527 mi
Registration #8	2018-02-15	53.325 mi
Registration #9	2019-03-01	59.563 mi
Registration #10	2020-03-01	59.563 mi
Registration #11	2020-03-01	59.563 mi
Registration #12	2020-03-01	59.563 mi
Registration #13	2020-03-01	59.563 mi
Registration #14	2020-03-01	59.563 mi
Registration #15	2020-03-01	59.563 mi
Registration #16	2020-03-01	59.563 mi
Registration #17	2020-03-01	59.563 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1493 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	732161