





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Grey
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date	2022-01-20
Date	2022-01-20

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-01-19
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



KS13MWG
report date: 2024-03-28

MOT history

MOT expiry date	2024-07-31
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #11	2023-07-20 14:50
MOT test number	211525102641
Result	✓ Passed
Next expiry date	2024-07-31

MOT #10	2022-08-01 13:21
MOT test number	570646419709
Result	✓ Passed

MOT #9	2021-07-12 09:16
MOT test number	112752493152
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2021-07-12 09:16
MOT test number	907997962978
Result	★ Failed
Pass with rectification (c))	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

Advice

Rear both tyres worn out of shape

MOT #6

MOT test number

238402531725

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge 155/65R14 75t 3mm (5.2.3 (e))

MOT test number

Result

Pass with rectification

Front Windscreen washer not working (3.5 (a))

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 155/65R14 75t 3mm (5.2.3 (e))

MOT #4 2018-07-10 14:53

MOT test number 102893019263

Result ✓ Passed

MOT #3

MOT test number

Result

Advice Offside Front Brake pad(s) wearing thin (AT LIMIT) (3.5.1g)


Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



report date: 2024-03-28





CarCheck.co.uk page 5/12



KS13MWG
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	IIK Sils
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-25
Last registration	2023-07-20
Complete history	See info



Registration #1	2013-06-25	13 mi
Registration #2	2016-06-25	19.275 mi
Registration #3	2017-07-25	26.629 mi
Registration #4	2017-07-25	26.629 mi
Registration #5	2018-07-10	31.608 mi
Registration #6	2019-07-23	35.509 mi
Registration #7	2019-07-23	35.509 mi
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00
Registration #12 Registration #13		11.77 44

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



KS13MWG
report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12