



RENAULT

HV08BKD

report date: 2024-03-28

General information

Make	RENAULT
Model	MASTER LH35 LWB L/C P/V 120
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	2.464 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-08
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2022-12-06
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	24
Total items failed	17

MOT #19	2021-12-07 14:17
MOT test number	360930253269
Result	✓ Passed
Next expiry date	2022-12-06
Advice	Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2021-11-29 10:15
MOT test number	278436224402
Result	✗ Failed
Fail	Nearside Seat belt buckle not functioning as intended (7.1.2 (d))
Advice	Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #17** 2021-10-25 15:47**MOT test number** 161807213265**Result** ✗ Failed

- Fail** Nearside Front Outer Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Offside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Brake cable has restricted free movement (1.1.15 (e))
- Minor** Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16 2020-05-05 14:42**MOT test number** 788823512851**Result** ✓ Passed**MOT #15** 2020-05-05 07:57**MOT test number** 398602947653**Result** ✗ Failed

- Fail** Nearside Rear Anti-roll bar attachment bracket/mounting missing (5.3.3 (a) (ii))
- Minor** Nearside Rear Outer Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #14 2019-04-30 08:34**MOT test number** 120720748179**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2018-05-01 09:16**MOT test number** 847626918353**Result** ✓ Passed**MOT #12** 2017-04-24 15:29**MOT test number** 710298168590**Result** ✓ Passed**MOT #11** 2017-04-24 09:08**MOT test number** 323413903185**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #10** 2016-04-26 09:00**MOT test number** 887878609104**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #9** 2016-04-19 07:48**MOT test number** 243839443534**Result** ✗ Failed**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #8** 2015-05-01 11:26**MOT test number** 598781225180**Result** ✓ Passed

**MOT #7**

2015-04-30 13:38

MOT test number

437320625169

Result**✗ Failed****Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** N/s/f outer c.v gaitor expelling grease**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #6**

2014-04-23 09:57

MOT test number

825363014145

Result**✓ Passed****Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5**

2014-04-23 09:57

MOT test number

865693814185

Result**✗ Failed****Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #4** 2013-04-16 16:50**MOT test number** 897246603117**Result** ✓ Passed

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #3 2013-04-16 11:39**MOT test number** 426276403125**Result** ✗ Failed

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #2 2012-04-27 17:29**MOT test number** 775268712106**Result** ✓ Passed

Advice Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Notice Nail in offside rear tyre

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #1 2011-05-05 15:08**MOT test number** 986545321184**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 March 2023

✕
MOT

Expired:
6 December 2022

Tax status

Expired at 31 March 2023

Days left

394 days too late

MOT expiry date

6 December 2022

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT
Date of agreement	2024-03-28
Agreement type	RENAULT
Agreement term	RENAULT
Agreement number	RENAULT
Contact info	RENAULT

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-27
Last registration	2021-12-07
Complete history	See info



Registration #1	2008-03-27	12 mi
Registration #2	2011-05-05	56.885 mi
Registration #3	2012-04-27	60.762 mi
Registration #4	2013-04-16	64.720 mi
Registration #5	2013-04-16	64.720 mi
Registration #6	2014-04-23	69.937 mi
Registration #7	2015-04-30	75.702 mi
Registration #8	2015-05-01	75.703 mi
Registration #9	2016-04-19	80.996 mi
Registration #10	2016-04-26	81.098 mi
Registration #11	2016-05-20	81.217 mi
Registration #12	2016-06-20	81.337 mi
Registration #13	2016-07-20	81.457 mi
Registration #14	2016-08-20	81.577 mi
Registration #15	2016-09-20	81.697 mi
Registration #16	2016-10-20	81.817 mi
Registration #17	2016-11-20	81.937 mi
Registration #18	2016-12-20	82.057 mi
Registration #19	2017-01-20	82.177 mi
Registration #20	2017-02-20	82.297 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2359 mm
Height	2200 mm
Length	6330 mm

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C155541