



SB6IDL D

report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-21
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	37
Total items failed	21

MOT #16	2024-04-22 10:38
MOT test number	152012137174
Result	✓ Passed
Next expiry date	2025-04-21
Advice	Exhaust flexi worn and loose
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #15**

2024-04-09 10:23

MOT test number

290696051954

Result**✗ Failed**

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Nearside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material tip of brake pipe (1.1.11 (c))
- Fail** Brake performance unable to be tested leaking brake pipe (1.2.1 (g))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))
- Advice** Exhaust flexi worn and loose
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Brake pipe corroded, covered in grease or other material tip of brake pipe (1.1.11 (c))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14

2023-03-02 15:45

MOT test number

880635327020

Result**✓ Passed****MOT #13**

2022-03-03 16:55

MOT test number

937858825724

Result**✓ Passed**

- Advice** Front Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))

**MOT #12** 2022-03-03 16:55**MOT test number** 316774085939**Result** ✗ Failed**Pass with rectification** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Front Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))**MOT #11** 2021-01-21 11:40**MOT test number** 613717628780**Result** ✓ Passed**MOT #10** 2021-01-20 16:38**MOT test number** 258385848874**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #9** 2020-02-10 14:59**MOT test number** 837266834346**Result** ✓ Passed**Advice** Rear Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Brake pipes corroded, covered in grease or other material**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Slight knock from rear suspension

**MOT #8** 2020-02-03 10:32**MOT test number** 678306547970**Result** ✗ Failed**Advice** Brake pipes corroded, covered in grease or other material**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Slight knock from rear suspension**Advice** Rear Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #7** 2019-02-05 12:50**MOT test number** 493511800573**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Slight knock from rear suspension

**MOT #6**

2019-01-21 11:49

MOT test number

216652056997

Result**✗ Failed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Brake hose excessively twisted (1.1.12 (b) (ii))
- Fail** Nearside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #5

2018-01-19 14:42

MOT test number

907248393559

Result**✓ Passed**

- Advice** Both front tyres worn partly on legal limit
- Advice** Offside Rear rear differential bush torn
- Advice** Offside Front suspension arm bush split but not resulting in excessive movement, front bush
- Advice** Nearside Front suspension arm bush split but not resulting in excessive movement, front bush

MOT #4

2017-01-24 12:26

MOT test number

793147602537

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Covers fitted to lower engine bay and under body obscuring inspection of testable items

**MOT #3** 2017-01-07 13:51**MOT test number** 681392672585**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Under-trays fitted obscuring some underside components
- Advice** Items removed from driver's view prior to test
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine covers fitted obscuring some components in the engine bay
- Fail** Parking brake lever has no reserve travel (3.1.6b)

MOT #2 2015-12-02 14:17**MOT test number** 485680250129**Result** ✓ Passed**MOT #1** 2014-12-02 11:52**MOT test number** 357216434366**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 April 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	21 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SB61DLD
Plate since	2019-03-29
Current registration	SB61DLD
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-11-30
Last registration	2024-04-22
Complete history	See info



Registration #1	2011-11-30	10 mi
Registration #2	2014-12-02	20.060 mi
Registration #3	2015-12-02	28.857 mi
Registration #4	2017-01-07	42.001 mi
Registration #5	2017-01-24	42.023 mi
Registration #6	2018-01-19	51.259 mi
Registration #7	2019-01-21	61.167 mi
Registration #8	2019-02-05	61.183 mi
Registration #9	2020-02-03	72.254 mi
Registration #10	2020-05-20	75.377 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi
Registration #16	2020-05-20	75.377 mi
Registration #17	2020-05-20	75.377 mi
Registration #18	2020-05-20	75.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBBH023291