





report date: 2024-03-28

### General information

Make	FORD
Model	TRANSIT CONNECT 200 P/V
Colour	White
Year of manufacture	2017
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	99 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	58.9 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-31

Pictures 1

Listing price <u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MD17DXB report date: 2024-03-28

MOT history

MOT expiry date	2025-01-30
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #7	2024-01-22 09:06
MOT test number	703452772359
Result	✓ Passed
Next expiry date	2025-01-30

MOT #6	2023-01-04 16:56
MOT test number	873719163346
Result	✓ Passed
Minor Offside Registration plate lamp inoperative in the case of multiple lamps o (i))	r light sources (4.7.1 (b)
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Nearside Front Tyre obviously under inflated (5.2.3 (I))	

MOT #5		2022-01-31 16:12
MOT test	t number	303174171656
Result		✓ Passed
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1 (b)
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2022-01-31 09:29

MOT test number 319655656183

Result X Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Rear bumper trim loose

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2021-01-21 10:28

**MOT test number** 300195110703

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Nail in tyre

MOT #2 2020-06-16 08:52

**MOT test number** 100426374395

**MOT #1** 2020-06-16 08:52

MOT test number 376535502820

**Result** X Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIZ
Plate since	
	More info

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-07-17
Last registration	2024-01-22
Complete history	See info



Registration #1	2017-07-17	25 mi
Registration #2	2020-06-16	56.318 mi
Registration #3	2020-06-16	56.318 mi
Registration #4	2021-01-21	59.644 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

The FORD factory car options list is only available in the premium report.	
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle <u>here</u>.

More info >

# Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	62%
Safety systems	70%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2137 mm
Height	1861 mm
Length	4418 mm
Kerb weight	1425 kg
Max. allowed weight	2000 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number CarCheck.co.uk	HG63775 page 11/11