





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLA CLA220 CDI AMG SPORT
Colour	White
Year of manufacture	2014
Top speed	143 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	125 kW / 170 HP / 170 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-08-05

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-31
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	15
Total items failed	3

MOT #8		2023-08-31 08:32
MOT test	number	700444791664
Result		✓ Passed
Next expi	y date	2024-08-31
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		kened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2022-09-01 12:05
MOT test number	827969308303
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	

CarCheck.co.uk page 3/12



MOT #6 2022-08-31 10:52

MOT test number 404503101044

Result × Failed

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))

MOT #5 2021-08-10 11:06

MOT test number 839507355218

Result Passed

Advice Offside Rear Nail in tyre

MOT #4 2020-11-14 08:42

MOT test number 385020202420

Result
✓ Passed

MOT #3 2019-05-14 08:32

MOT test number 513588026169

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #2	2018-04-23 13:42
MOT test number	712722479362
Result	✓ Passed
MOT #1	2017-05-13 08:28
MOT test number	227414342124
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



SF64XCE

report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NE CITY OF THE CIT
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-01
Last registration	2023-08-31
Complete history	See info



Registration #1	2014-09-01	27 mi
Registration #2	2017-05-13	28.641 mi
Registration #3	2018-04-23	32.662 mi
Registration #4	2019-05-14	39.850 mi
Registration #5	2020-11-14	48.728 mi
Registration #6		10 JUL 44
•		
Registration #7		11.777 es
Registration #7 Registration #8		11.777 ea
		11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



SF64XCE

report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1525 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack caluk	200 12/1

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	65193032120397