





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Grey
Year of manufacture	-
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/11



YK06VWX
report date: 2024-03-29

MOT history

MOT #14	2020-09-14 09:15
MOT test number	205498100867
Result	✓ Passed

Next expiry date 2021-09-14

MOT #13 2019-09-10 15:47

MOT test number 708963000542

Result ✓ Passed

MOT #12 2018-09-15 15:45

MOT test number 250054136525

Result ✓ Passed

Advice Rear both rear springs corroded

Advice Under body corroded

MOT #11 2017-11-06 14:23

MOT test number 391675887037

Result ✓ Passed

MOT #10 2017-11-06 11:59

MOT test number 637754135548

Result × Failed

Fail Nearside Front Brake hose ferrule excessively corroded (3.6.B.4e)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Offside Front Brake hose ferrule excessively corroded (3.6.B.4e)

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #9		2016-11-05 11:12
MOT test	number	231184563504
Result		✓ Passed
Advice	Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Nearside Rear tyre cracking in tread path	
Advice	Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Offside Rear lens holed	
Advice	Offside Rear tyre cracking in tread path	

MOT #8	2016-10-28 13:23
MOT test number	857803053504
Result	× Failed
Advice Offside Rear tyre cracking in tread path	
Advice Offside Front Headlamp damaged but light output not reduced (1.7.5a)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Offside Front bumper damaged	
Advice Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice Nearside Rear tyre cracking in tread path	
Fail Offside Front Headlamp aim too low (1.8)	
Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Advice Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice Offside Rear lens holed	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #7		2015-07-31 12:33
MOT test	number	509842315278
Result		✓ Passed
Notice	Oil leak	
Notice	Non obligatory mirror damaged	
Notice	Under-trays fitted obscuring some underside components	

MOT #6	2013-08-16 13:09
MOT test number	666458223233
Result	✓ Passed
MOT #5	2013-08-12 16:56

MOT test number 385504423271

Result X Failed

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #4	2012-08-16 15:30
MOT test number	738879022259
Result	✓ Passed
MOT #3	2011-08-10 16:34
MOT test number	968222921221
Result	✓ Passed
MOT #2	2010-08-13 09:13
MOT test number	264505820260
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #1 2009-08-14 13:06

MOT test number 861296929291

Result ✓ Passed

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Notice O/s/f & n/s/f & n/s/r tyre walls cracking

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2
Date



Туре

Category

Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



-

YK06VWX

report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.

More info >

CarCheck.co.uk page 8/11



YK06VWX report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 9/11



YK06VWX report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-08-19
Last registration	2020-09-14
Complete history	See info



Registration #1	2006-08-19	23 mi
Registration #2	2009-08-14	12.066 mi
Registration #3	2010-08-13	19.279 mi
Registration #4	2011-08-10	25.407 mi
Registration #5	2012-08-16	31.579 mi
Registration #6	2013-08-12	37.273 mi
Registration #7	2013-08-16	37.273 mi
Registration #8	2015-07-31	45.948 mi
Registration #9		9.77 es
Registration #10		11.777 es
Registration #11		9.77 m
Registration #12		11.777 es
Registration #13		9.377 es
Registration #14		0.00 44
Registration #15		11,177 mi

More info >

CarCheck.co.uk page 10/11



YK06VWX report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	★★★★ ★
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChack caluk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	4
Number of axles	2
Engine number	BMD 255340