



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.600 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-12-14
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-13
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-12-19
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	11
Total items failed	5

MOT #17	2023-12-20 11:53
MOT test number	906111173924
Result	✓ Passed
Next expiry date	2024-12-19
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2022-12-12 13:31
MOT test number	581485433331
Result	✓ Passed
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2022-12-12 11:45
MOT test number	176674644362
Result	✗ Failed
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Central Front Lower Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))

**MOT #14** 2021-12-16 17:16**MOT test number** 834562020677**Result** ✓ Passed**MOT #13** 2021-05-27 09:07**MOT test number** 651444135036**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**Advice** Nearside Play in steering rack inner joint(s)**MOT #12** 2020-06-16 15:04**MOT test number** 486289061406**Result** ✓ Passed**Advice** Nearside Front Outer Tyre slightly damaged Sidewall (5.2.3 (d) (ii))**MOT #11** 2019-05-08 12:42**MOT test number** 734596841595**Result** ✓ Passed**MOT #10** 2018-05-15 08:36**MOT test number** 810937636973**Result** ✓ Passed

**MOT #9** 2018-05-14 14:41**MOT test number** 255905209106**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #8** 2017-05-11 11:25**MOT test number** 647375480172**Result** ✓ Passed**MOT #7** 2016-05-10 09:22**MOT test number** 596199045277**Result** ✓ Passed**Advice** Front discs corroded on inside edges**MOT #6** 2015-05-12 11:39**MOT test number** 645612135133**Result** ✓ Passed**MOT #5** 2014-05-16 11:55**MOT test number** 567186334166**Result** ✓ Passed**MOT #4** 2013-05-03 13:44**MOT test number** 906433023150**Result** ✓ Passed



MOT #3	2013-05-03 10:52
MOT test number	349853923150
Result	✗ Failed
<div>Fail</div> Stop lamp not working (1.2.1b)	

MOT #2	2012-05-09 11:13
MOT test number	707260332194
Result	✓ Passed

MOT #1	2011-05-18 11:33
MOT test number	927078731114
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
19 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	19 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 RJ08HZH
Plate since	2024-03-29
Current registration	 RJ08HZH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-28
Last registration	2023-12-20
Complete history	<a href="#">See info</a>



Registration #1	2008-05-28	18 mi
Registration #2	2011-05-18	7.690 mi
Registration #3	2012-05-09	10.099 mi
Registration #4	2013-05-03	12.194 mi
Registration #5	2013-05-03	12.194 mi
Registration #6	2014-05-16	14.098 mi
Registration #7	2015-05-12	15.310 mi
Registration #8	2016-05-10	16.788 mi
Registration #9	2017-05-11	17.959 mi
Registration #10	2018-05-14	19.068 mi
Registration #11	2019-05-20	20.277 mi
Registration #12	2019-05-20	20.277 mi
Registration #13	2019-05-20	20.277 mi
Registration #14	2019-05-20	20.277 mi
Registration #15	2019-05-20	20.277 mi
Registration #16	2019-05-20	20.277 mi
Registration #17	2019-05-20	20.277 mi
Registration #18	2019-05-20	20.277 mi
Registration #19	2019-05-20	20.277 mi
Registration #20	2019-05-20	20.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1215 kg
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	20LS3816