



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Red
Year of manufacture	-
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-25
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #15</b>	2021-10-22 12:42
<b>MOT test number</b>	954958234009
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-21

<b>MOT #14</b>	2021-10-22 10:00
<b>MOT test number</b>	942110593666
<b>Result</b>	✗ Failed

- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

<b>MOT #13</b>	2020-10-22 15:12
<b>MOT test number</b>	201627791302
<b>Result</b>	✓ Passed

- Advice** Offside Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2020-10-22 12:29**MOT test number** 345995828706**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Advice** Offside Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**MOT #11** 2019-05-21 12:18**MOT test number** 619989311180**Result** ✓ Passed**Advice** Bind on o/s/f brake**Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #10**

2019-05-21 08:53

**MOT test number**

149808222943

**Result**

✗ Failed

**Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Bind on o/s/f brake**MOT #9**

2018-05-24 15:23

**MOT test number**

425162345341

**Result**

✓ Passed

**Advice** Exhaust blow from front flange**Advice** Slight play in o/s/f steering arm**MOT #8**

2017-05-23 14:48

**MOT test number**

431761196738

**Result**

✓ Passed

**Advice** 1 rear exhaust mounting broken**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2016-05-18 10:05

**MOT test number**

916722014929

**Result**

✓ Passed



<b>MOT #6</b>	2015-06-03 15:55
<b>MOT test number</b>	245124555168
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2014-06-06 11:41
<b>MOT test number</b>	379377354149
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2013-06-05 15:38
<b>MOT test number</b>	288176253400
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2012-05-30 15:27
<b>MOT test number</b>	286051152169
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2011-06-02 14:41
<b>MOT test number</b>	235763851411
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2010-06-11 09:49
<b>MOT test number</b>	294002460414
<b>Result</b>	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	<b>BP07XKZ</b>
Plate since	2024-03-29
Current registration	<b>BP07XKZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-08-15
Last registration	2021-10-22
Complete history	<a href="#">See info</a>



Registration #1	2007-08-15	11 mi
Registration #2	2010-06-11	16.654 mi
Registration #3	2011-06-02	24.363 mi
Registration #4	2012-05-30	33.505 mi
Registration #5	2013-06-05	41.419 mi
Registration #6	2014-06-06	48.426 mi
Registration #7	2015-06-03	54.096 mi
Registration #8	2016-05-18	58.816 mi
Registration #9	2017-05-23	64.832 mi
Registration #10	2018-05-23	71.277 mi
Registration #11	2019-05-23	78.277 mi
Registration #12	2020-05-23	85.277 mi
Registration #13	2021-05-23	92.277 mi
Registration #14	2022-05-23	99.277 mi
Registration #15	2023-05-23	106.277 mi
Registration #16	2024-05-23	113.277 mi
Registration #17	2025-05-23	120.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3245520