





General information

Make	ΤΟΥΟΤΑ
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Silver
Year of manufacture	2011
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	169 BHP	0 < 101 A
Max. torque	343 Nm at 3.400 rpm	101 - 120 ^B _C
Engine capacity	2.982 cc	121 - 140 E
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185 H
Consumption city	29.7 mpg	186 - 225 J
Consumption extra urban	42.2 mpg	225+ L
Consumption combined	36.7 mpg	





Internet history

Entry	1
Date	

2021-07-16

32

Listing price

Pictures

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-16
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	13
Total items failed	10

MOT #19		2023-09-11 09:03
MOT test n	umber	924582191236
Result		🗸 Passed
Next expiry	y date	2024-09-16
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner shoulder (5.2.3 (e))		shoulder (5.2.3 (e))
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on inner sh	oulder (5.2.3 (e))

MOT #18		2023-09-11 09:03
MOT test number		753815252116
Result		🗙 Failed
Advice Nearside Front	Γyre worn close to legal limit/worn on edge Worr	n on inner shoulder (5.2.3 (e))
Advice Rear Exhaust ha	as a minor leak of exhaust gases (6.1.2 (a))	
Pass with rectification	Nearside Rear Position lamp not working (4.2.	1 (a) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge Worn on inner shoulder (5.2.3 (e))		
Pass with rectification	Nearside Front Position lamp not working (4.2	.1 (a) (ii))





MOT #17		2022-09-16 08:16
MOT test	number	963315752317
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2021-09-17 17:26
MOT test number	799025052450
Result	✓ Passed
Advice Emissions too clean	

MOT #15	2021-06-23 14:44
MOT test number	475283996542
Result	✓ Passed
Advice Brake pipe corroded, covered in grease or other material all brake p (1.1.11 (c))	ipes covered in grease.

MOT #14	2020-07-03 11:19
MOT test number	412092484073
Result	✓ Passed

MOT #13		2020-07-02 13:06
MOT test	number	853628961271
Result		🗙 Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2019-09-11 08:34
MOT test number	664712065843
Result	✓ Passed





MOT #11		2018-09-12 10:46
MOT test number		318311577541
Result		✓ Passed
MOT #10		2018-09-12 10:46
MOT test number		169790001432
Result		× Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
MOT #9		2017-09-20 13:50
MOT test number		353304804299
Result		✓ Passed
MOT #8		2017-09-20 09:45
MOT test number		871045224906
Result		🗙 Failed
Fail Offside Rear fog lamp not working (1.3.2b)		
Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)		

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
Fail Stop lamp not working all brake lights inop (1.2.1b)
Advice Offside Front Inner Suspension arm has slight play in a pin/bush (2.4.G.2)
Fail Electronic stability system warning lamp indicates a fault (3.4.1c)

MOT #7	2016-11-01 14:45
MOT test number	599492622044
Result	✓ Passed





MOT #6	2016-10-31 11:47
MOT test number	618246904860
Result	🗙 Failed
Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)	
MOT #5	2016-02-01 11:35
MOT test number	563959427956
Result	✓ Passed
MOT #4	2015-01-23 08:48
MOT test number	157083825401
Result	✓ Passed
MOT #3	2015-01-22 10:38
MOT test number	649242725043
Result	🗙 Failed
Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3)	
MOT #2	2014-01-29 16:41
MOT test number	417369424004
Result	✓ Passed
MOT #1	2014-01-29 16:41
MOT test number	457349224006
Result	🗙 Failed
Pass with rectification Main beam 'tell-tale' not working (1.7.4c)	



VN60UDP report date: 2024-03-29

Tax & MOT check







Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	Lamp
Туре	
Damage 2	AMPL
Date	Nº I
Category	ANNY.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



VN60UDP report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-02-03
Last registration	2023-09-11
Complete history	<u>See info</u>



Registration #1	2011-02-03	26 mi
Registration #2	2014-01-29	16.324 mi
Registration #3	2015-01-22	21.890 mi
Registration #4	2015-01-23	21.891 mi
Registration #5	2016-02-01	27.913 mi
Registration #6	2016-10-31	33.626 mi
Registration #7	2016-11-01	33.626 mi
Registration #8	2017-09-20	41.381 mi
Registration #9	2017-09-20	41.381 mi
Registration #10	2018-09-12	57.211 mi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 mi
Registration #20		11.117 mi





Car features

S0225	Air conditionin
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	1975 kg
Max. allowed weight	3080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD5220094