





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/16



Internet history

Entry 1

Date 2022-01-16

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2025-02-13
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	44
Total items failed	24

MOT #16		2024-02-14 15:08
MOT test	number	222558849726
Result		✓ Passed
Next expi	ry date	2025-02-13
Advice Advice	Nearside Rear Tyre worn close to legal limit/worn on edge bald on one of the control of the cont	

CarCheck.co.uk page 3/16



Fail

**KW12DGZ** 

report date: 2024-03-28

**MOT #15** 2024-02-08 12:30

MOT test number 922009272470

Result **X** Failed Fail Offside Headlamp not working on main beam (4.1.1 (a) (ii)) Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.mm bald on inner shoulder (5.2.3 (e)) Fail Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii)) Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii)) Fail Offside Headlamp aim unable to be tested (4.1.2 (b)) Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii)) Nearside Rear Tyre worn close to legal limit/worn on edge bald on outer shoulder (5.2.3 (e)) **Advice** 

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-28

### MOT #14 2023-02-14 16:28

**MOT test number** 960480326042

MO1 test	t number 90048032	0042
Result	✓ Pa	ssed
Advice	Coolant low	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor	Windscreen damaged but not adversely affecting driver's view small chip in centre (3.2 (a) (i))	
Advice	Heat shield loose	
Advice	Rear Direction indicator slightly discoloured both (4.4.3 (a))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Both front tyres inner edges starting to go bald	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	

CarCheck.co.uk page 5/16



**Advice** 

**KW12DGZ** 

report date: 2024-03-28

**MOT #13** 2023-02-03 16:51 **MOT** test number 629602367878 Result **X** Failed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Play in steering rack inner joint(s) Both front tyres inner edges starting to go bald Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Coolant low Advice Fail Offside Front Headlamp aim too high (4.1.2 (a)) Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Minor Windscreen damaged but not adversely affecting driver's view small chip in centre (3.2 (a) (i)) Heat shield loose Advice

MOT #12	2022-01-14 08:48
MOT test number	514229537831
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Rear Direction indicator slightly discoloured both (4.4.3 (a))

CarCheck.co.uk page 6/16



report date: 2024-03-28

**MOT #11** 2022-01-13 14:24 **MOT** test number 621032590624 Result × Failed Fail Offside Headlamp aim too high (4.1.2 (a)) Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Headlamp aim too high (4.1.2 (a)) **Advice** Rear Exhaust mounting defective (6.1.2 (a)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #10

MOT test number

Result

Advice

Rear Tyre slightly damaged/cracking or perishing both rear worn on edges (5.2.3 (d) (ii))

MOT #9

MOT test number

562856886824

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 7/16



MOT #8 2020-07-08 12:49

MOT test number 576363140764

**Result** X Failed

**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #7** 2019-05-07 07:20

**MOT test number** 125642041690

Result Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #6** 2019-05-02 11:14

**MOT test number** 587974049863

Result × Failed

**Minor** Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))

Fail Offside Rear Position lamp not working (4.2.1 (a))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Exhaust system insecure (6.1.2 (a))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 8/16



report date: 2024-03-28

**MOT #5** 2018-05-22 15:18

**MOT test number** 746205977043

Result \rightarrow Passed

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Exhaust hangars badly welded with slight leak of exhaust gasses at front hangar

**MOT #4** 2017-06-17 09:47

MOT test number 179653117406

Result \( \sqrt{Passed} \)

**Advice** Slight brake bind starting to nearside front

MOT #3 2016-06-21 12:05

MOT test number 355830859505

**Result** ✓ Passed

**Advice** Front brake pads approaching replacement stage

Advice Both front tyres wearing inner edges and starting to blister approaching fail stage

MOT #2 2016-06-21 12:05

**MOT test number** 918530470373

Result × Failed

**Pass with rectification** Exhaust system not adequately supported (7.1.1)

**Advice** Both front tyres wearing inner edges and starting to blister approaching fail stage

**Advice** Front brake pads approaching replacement stage

**MOT #1** 2015-06-27 12:03

**MOT test number** 609688475193

CarCheck.co.uk page 9/16



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	13 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



·

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

# Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*******	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 13/16



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 14/16



## Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-27
Last registration	2024-02-14
Complete history	See info



Registration #1	2012-06-27	26 mi
Registration #2	2015-06-27	39.881 mi
Registration #3	2016-06-21	51.983 mi
Registration #4	2016-06-21	51.983 mi
Registration #5	2017-06-17	63.243 mi
Registration #6	2018-05-22	72.141 mi
Registration #7	2019-05-02	79.961 mi
Registration #8	2019-05-07	80.075 mi
Registration #9	2020-07-08	87.217 mi
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 15/16



Car features

S0225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1815 mm
Height	1498 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1410 kg
Max. allowed weight	1800 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 16/16

Number of axles 2

Engine number JBEE0158928