





report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Black
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 3.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg
CO2 emission	203 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-19

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

Advice

MOT expiry date	2024-11-30
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	16
Total items failed	0

MOT #8	2023-11-17 16:02
MOT test number	284770947613
Result	✓ Passed
Next expiry date	2024-11-30
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2022-11-16 15:01
MOT test number	818492282642
Result	✓ Passed

MOT #6	2021-12-01 09:16
MOT test number	887428897061
Result	✓ Passed

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. across the front axel (1.2.1 (b) (i))

Vehicles internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 3/12



MOT #5 2020-11-26 14:35

MOT test number 128339831929

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2020-11-25 08:50

MOT test number 377700555269

Result X Failed

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-05-16 13:59

MOT test number 843986198437

Result ✓ Passed

Advice Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

MOT #2 2018-05-29 08:57

MOT test number 286482321990

CarCheck.co.uk page 4/12



MOT #1

MOT test number

964657849916

Result

Advice Nearside Rear Nail in tyre

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

HEREERS	

THE STREET STREET	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-05-30
Last registration	2023-11-17
Complete history	See info



Registration #1	2014-05-30	8 mi
Registration #2	2017-05-11	27.478 mi
Registration #3	2018-05-29	37.932 mi
Registration #4	2019-05-16	44.571 mi
Registration #5	2020-11-25	63.155 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
-		11.77 m
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	2135 kg
Max. allowed weight	3080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KDA429776

CarCheck.co.uk page 12/12