



DA6IXBG

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | 2 TAMURA |
| Colour | Blue |
| Year of manufacture | 2012 |
| Top speed | 107 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 83 BHP |
| Max. torque | 121 Nm at 3.500 rpm |
| Engine capacity | 1.349 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 45.6 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 115 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-01 |
| Pictures | 10 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-25 |
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 5 |

| | |
|------------------|---|
| MOT #12 | 2023-05-19 15:34 |
| MOT test number | 636100723213 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-25 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|--|
| MOT #11 | 2023-05-19 08:28 |
| MOT test number | 912469374155 |
| Result | ✗ Failed |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Fail | Front Shock absorbers has negligible damping effect both (5.3.2 (d)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |
| Fail | Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

**MOT #10** 2022-05-19 07:49**MOT test number** 830189139978**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2021-05-26 13:44**MOT test number** 746623304861**Result** ✓ Passed**MOT #8** 2020-09-29 12:17**MOT test number** 744675016174**Result** ✓ Passed**MOT #7** 2019-12-11 14:03**MOT test number** 126975657116**Result** ✓ Passed**MOT #6** 2018-12-11 10:37**MOT test number** 213843356638**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Limited underbody inspection due to undershields.**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5** 2018-12-11 10:37**MOT test number** 393667859316**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Limited underbody inspection due to undershields.**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2017-12-13 11:29**MOT test number** 377734228252**Result** ✓ Passed**MOT #3** 2016-12-13 14:42**MOT test number** 812738633885**Result** ✓ Passed**MOT #2** 2015-12-15 15:20**MOT test number** 769837909114**Result** ✓ Passed**MOT #1** 2014-12-16 15:21**MOT test number** 617990754385**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 25 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2012-01-21 |
| Last registration | 2023-05-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-01-21 | 9 mi |
| Registration #2 | 2014-12-16 | 6.789 mi |
| Registration #3 | 2015-12-15 | 8.343 mi |
| Registration #4 | 2016-12-13 | 9.704 mi |
| Registration #5 | 2017-12-13 | 11.160 mi |
| Registration #6 | 2018-12-11 | 12.218 mi |
| Registration #7 | 2018-12-11 | 12.218 mi |
| Registration #8 | 2019-05-20 | 15.277 mi |
| Registration #9 | 2019-05-20 | 15.277 mi |
| Registration #10 | 2019-05-20 | 15.277 mi |
| Registration #11 | 2019-05-20 | 15.277 mi |
| Registration #12 | 2019-05-20 | 15.277 mi |
| Registration #13 | 2019-05-20 | 15.277 mi |
| Registration #14 | 2019-05-20 | 15.277 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1695 mm |
| Height | 1475 mm |
| Length | 3885 mm |
| Wheel base | 2490 mm |
| Kerb weight | 1025 kg |
| Max. allowed weight | 1485 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 42 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | ZJ A50824 |