





## General information

Make	MAZDA
Model	5 D VENTURE EDITION
Colour	White
Year of manufacture	2013
Top speed	111 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E







Internet history	
Entry 1	
Date	2021-10-29
Pictures	0
Listing price	View report

source: autotrader.co.uk



# MOT history

MOT expiry date	2022-11-01
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #8	2021-11-02 13:04
MOT test number	126443655891
Result	✓ Passed
Next expiry date	2022-11-01

MOT #7	2021-	02-23 12:25
MOT test	number 342	2710133246
Result		🗸 Passed
Advice	Nearside Rear Nail in tyre	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		t (5.3.4 (a)
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened $(1.1.14$ (a) (ii))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #6		2020-03-10 14:10
MOT test	number	380971504618
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))	





MOT #5		2019-03-05 15:51
MOT test	number	418186843564
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
MOT #4		2019-03-05 10:46

MOT test number	379748942784
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Stop lamp(s) all not working (4.3.1 (a) (iii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2018-03-08 11:03
MOT test number	932124190083
Result	✓ Passed
Advice Under trays fitted	
Advice Both rear tyres starting to crack	

MOT #2	2017-02-18 08:45
MOT test number	445161183261
Result	✓ Passed

MOT #1	2016-03-08 16:38
MOT test number	894589038912
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 28 February 2023	<b>X</b> <b>MOT</b> Expired: 1 November 2022
Tax status	Expired at 28 February 2023
Days left	426 days too late
MOT expiry date	1 November 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





## Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ARANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	*
Category	AMP
Туре	

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	
**********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-03-08
Last registration	2021-11-02
Complete history	See info



Registration #1	2013-03-08	21 mi
Registration #2	2016-03-08	17.712 mi
Registration #3	2017-02-18	27.002 mi
Registration #4	2018-03-08	38.166 mi
Registration #5	2019-03-05	43.838 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.100 aug

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 l Indirect Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Indirect Injection
Fuel tank capacity Fuel delivery Number of doors	Indirect Injection 5