



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Blue
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-05-22
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-25
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	26
Total items failed	8

MOT #13	2023-09-26 16:23
---------	------------------

MOT test number	607321200364
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-25
------------------	------------

- AdviceFront Under-tray fitted
- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceRear Windscreen wiper blade defective (damaging mirror)
- AdviceNearside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceFront Brake pad(s) wearing thin both (1.1.13 (a) (ii))

**MOT #12**

2023-09-23 12:29

MOT test number

535389324516

Result**✗ Failed**

Fail Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt both (2.1.3 (g) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm bold (5.2.3 (e))

Advice Front Under-tray fitted

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Front Suspension arm ball joint excessively worn both (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Windscreen wiper blade defective (damaging mirror)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

MOT #11

2022-08-15 08:53

MOT test number

965810268999

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Items removed from driver's view prior to test air freshener

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Nearside Front Windscreen wiper blade defective getting split (3.4 (b) (i))

**MOT #10** 2022-08-12 09:40**MOT test number** 413559816950**Result** ✗ Failed**Advice** Items removed from driver's view prior to test air freshener**Minor** Nearside Front Windscreen wiper blade defective getting split (3.4 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2021-07-23 16:04**MOT test number** 569230377202**Result** ✓ Passed**MOT #8** 2021-07-23 14:59**MOT test number** 646026491756**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #7** 2020-11-06 10:41**MOT test number** 637736422028**Result** ✓ Passed**MOT #6** 2019-05-09 12:50**MOT test number** 202584301348**Result** ✓ Passed

**MOT #5** 2018-05-15 13:50**MOT test number** 129644835716**Result** ✓ Passed**Advice** Both rears and o/s/f tyres bald on inner edges**MOT #4** 2018-05-14 12:27**MOT test number** 238502038096**Result** ✗ Failed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Both rears and o/s/f tyres bald on inner edges**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #3** 2017-05-12 08:53**MOT test number** 974853464666**Result** ✓ Passed**MOT #2** 2015-12-15 15:22**MOT test number** 784638339708**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**MOT #1** 2015-12-14 18:13**MOT test number** 745308033690**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-13
Last registration	2023-09-26
Complete history	See info



Registration #1	2012-12-13	10 mi
Registration #2	2015-12-14	37.791 mi
Registration #3	2015-12-15	37.792 mi
Registration #4	2017-05-12	57.618 mi
Registration #5	2018-05-14	69.843 mi
Registration #6	2018-05-15	69.893 mi
Registration #7	2019-05-09	79.948 mi
Registration #8	2020-11-06	97.845 mi
Registration #9	2020-11-06	97.845 mi
Registration #10	2020-11-06	97.845 mi
Registration #11	2020-11-06	97.845 mi
Registration #12	2020-11-06	97.845 mi
Registration #13	2020-11-06	97.845 mi
Registration #14	2020-11-06	97.845 mi
Registration #15	2020-11-06	97.845 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	D4HBCU692526
---------------	--------------