



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Black
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-12
Pictures	36
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-04
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	14
Total items failed	7

MOT #18	2023-09-05 14:21
MOT test number	692257886230
Result	✓ Passed
Next expiry date	2024-09-04

MOT #17	2023-08-29 11:16
MOT test number	296112411500
Result	✗ Failed
Fail	Front Windscreen washer not working (3.5 (a))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #16	2022-04-01 08:43
MOT test number	283167221697
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2022-04-01 08:43**MOT test number** 773532685842**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #14** 2021-04-08 10:54**MOT test number** 946148060194**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Engine and underbody covers fitted restricted view**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #13** 2021-04-08 10:54**MOT test number** 375508702830**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Engine and underbody covers fitted restricted view**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #12** 2020-02-03 14:35**MOT test number** 809962952374**Result** ✓ Passed

**MOT #11** 2019-02-04 11:06**MOT test number** 740523116102**Result** ✓ Passed**MOT #10** 2017-11-30 15:45**MOT test number** 965164555046**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)**MOT #9** 2016-12-02 10:30**MOT test number** 815654079326**Result** ✓ Passed**MOT #8** 2015-11-10 12:01**MOT test number** 915938998391**Result** ✓ Passed**Advice** Rear tyres are perrishing**MOT #7** 2014-11-11 16:01**MOT test number** 288005014312**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2013-11-19 15:52**MOT test number** 948253923379**Result** ✓ Passed**MOT #5** 2012-11-29 12:55**MOT test number** 458794332498**Result** ✓ Passed

**MOT #4** 2012-11-20 13:03**MOT test number** 549895622392**Result** ✗ Failed**Fail** Nearside Obligatory mirror insecure (8.1.1)**MOT #3** 2011-11-29 10:40**MOT test number** 818733231329**Result** ✓ Passed**MOT #2** 2011-11-29 10:40**MOT test number** 696733931313**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #1** 2010-11-25 11:55**MOT test number** 793429620343**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
4 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	4 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>LR57UOD</b>
Plate since	2019-06-29
Current registration	<b>LR57UOD</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2023-09-05
Complete history	<a href="#">See info</a>



Registration #1	2007-11-30	20 mi
Registration #2	2010-11-25	12.512 mi
Registration #3	2011-11-29	15.750 mi
Registration #4	2012-11-20	18.026 mi
Registration #5	2012-11-29	18.026 mi
Registration #6	2013-11-19	20.128 mi
Registration #7	2014-11-11	21.212 mi
Registration #8	2015-11-10	22.457 mi
Registration #9	2016-12-02	23.263 mi
Registration #10	2017-11-30	26.129 mi
Registration #11	2018-11-29	26.129 mi
Registration #12	2019-11-29	26.129 mi
Registration #13	2020-11-29	26.129 mi
Registration #14	2021-11-29	26.129 mi
Registration #15	2022-11-29	26.129 mi
Registration #16	2023-11-29	26.129 mi
Registration #17	2024-11-29	26.129 mi
Registration #18	2025-11-29	26.129 mi
Registration #19	2026-11-29	26.129 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030376807