



General information

Make	VOLKSWAGEN
Model	SCIROCCO R DSG
Colour	White
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	265 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	187 g/km
CO2 label	J





MOT history

MOT expiry date	2023-05-31
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	44
Total items failed	19

MOT #15	2022-06-01 16:03
MOT test number	399435635960
Result	✓ Passed
Next expiry date	2023-05-31

MOT #14	2021-02-06 11:48
MOT test number	534172427278
Result	✓ Passed

MOT #13	2019-07-12 15:36
MOT test number	756821608984
Result	✓ Passed
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Front wheel showing signs of being welded
Advice	Offside Rear Nail in tyre x2 nails in the same tyre

**MOT #12** 2019-07-06 13:47**MOT test number** 327555595615**Result** ✗ Failed**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front wheel showing signs of being welded**Advice** Offside Rear Nail in tyre x2 nails in the same tyre**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2018-02-19 13:13**MOT test number** 206560614543**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2018-02-13 13:00**MOT test number** 427703426764**Result** ✗ Failed**Fail** Offside Front Headlamp levelling device obviously defective (1.7.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Suspension arm has excessive play in a pin/bush front bush (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2017-10-05 17:00**MOT test number** 944566948636**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement Front bush (2.4.G.2)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Rear Nail in tyre
- Fail** Offside Front Headlamp levelling device inoperative (1.7.2)
- Advice** Offside Rear Shocker cover insecure
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2016-09-03 11:22**MOT test number** 137853185476**Result** ✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front load/height sensor broken
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #7** 2016-09-03 08:16**MOT test number** 200356405993**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front load/height sensor broken**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Rear Brake pad(s) less than 1.5 mm thick disc replacement required. (3.5.1g)**MOT #6** 2016-06-15 12:01**MOT test number** 583432993587**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front headlamp height adj broken**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Engine covers and under trays fitted to the vehicle



MOT #5 2015-04-24 12:47

MOT test number 549024115182

Result ✓ Passed

- Notice** Tyre run flat light on
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2015-04-24 11:46

MOT test number 276804215485

Result ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Tyre run flat light on

**MOT #3** 2014-04-10 16:43**MOT test number** 117840104116**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #2 2014-04-09 15:58**MOT test number** 989179894026**Result** ✗ Failed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2013-03-08 16:10**MOT test number** 319377563053**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KT10WLE
Plate since	2019-06-29
Current registration	 KT10WLE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-31
Last registration	2022-06-01
Complete history	See info



Registration #1	2010-03-31	23 mi
Registration #2	2013-03-08	14.999 mi
Registration #3	2014-04-09	37.315 mi
Registration #4	2014-04-10	37.367 mi
Registration #5	2015-04-24	57.971 mi
Registration #6	2015-04-24	57.971 mi
Registration #7	2016-06-15	81.655 mi
Registration #8	2016-09-03	84.885 mi
Registration #9	2016-09-03	84.885 mi
Registration #10	2016-09-03	84.885 mi
Registration #11	2016-09-03	84.885 mi
Registration #12	2016-09-03	84.885 mi
Registration #13	2016-09-03	84.885 mi
Registration #14	2016-09-03	84.885 mi
Registration #15	2016-09-03	84.885 mi
Registration #16	2016-09-03	84.885 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CDL 022238