





report date: 2024-03-29

General information

Make	KIA
Model	PROCEED GT-LINE S ISG S-A GT-LINE S ISG
Colour	White
Year of manufacture	2019
Top speed	127 mph
0 - 100 km/h	9.1 seconds
0 - 60 mph	9.1 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	242 Nm at 1.500 rpm
Engine capacity	1.353 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	135 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



Internet history

Entry 5

Date	2024-03-25	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

Entry 4

Date	2023-08-03
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 3

Date	2023-07-28
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 2

Date	2022-07-28
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk


Entry 1

CarCheck.co.uk page 2/11

Date 2022-07-23


Pictures 26

Listing price <u>View report</u>











source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-04
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	6
Total items failed	1

MOT #5	2024-04-15 10:22
MOT test number	754202632470
Result	✓ Passed
Next expiry date	2025-05-04

MOT #4 2024-04-09 09:41

MOT test number 183493803212

Result X Failed

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure SIDEWALL (5.2.3 (d) (ii))

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure SIDEWALL (5.2.3 (d) (ii))

MOT #3	2023-05-05 12:28
MOT test number	875008131522
Result	✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



Pass with rectification

CA19CPU

report date: 2024-03-29

 MOT #2
 2022-03-28 05:00

 MOT test number
 671332875468

 Result
 ✓ Passed

 MOT #1
 2022-03-28 05:00

 MOT test number
 185578421753

 Result
 X Failed

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check

Tax expired: 20 March 2024





Tax status	Expired at 20 March 2024
Days left	39 days too late
MOT expiry date	4 May 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



CA19CPU

report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



CA19CPU

report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
Current registration	NK SING SING SING SING SING SING SING SING
Plate since	
	More info >

CarCheck.co.uk page 8/11



CA19CPU

report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2019-03-29
Last registration	2024-04-15
Complete history	See info



Registration #1	2019-03-29	20 mi
Registration #2	2022-03-28	1 mi
Registration #3	2022-03-28	1 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6	2023-05-05	48.669 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.777 au

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

Dim	ensior	2 2	MOIO	hŧ
	ensioi	15 (2	werd	ш

Width	1800 mm
Height	1422 mm
Length	4605 mm
Wheel base	2650 mm
Kerb weight	1405 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4LDK1033899

CarCheck.co.uk page 11/11