



General information

Make	VOLVO
Model	S60 D3 SE
Colour	White
Year of manufacture	2012
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-07-18
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2025-03-17
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	16
Total items failed	3

MOT #11	2024-03-14 08:14
MOT test number	947149542281
Result	✓ Passed
Next expiry date	2025-03-17

MOT #10	2023-03-16 07:50
MOT test number	524025368803
Result	✓ Passed

MOT #9	2022-03-17 09:40
MOT test number	395811746062
Result	✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2021-03-18 09:30
MOT test number	172645216747
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #7** 2021-03-18 09:30**MOT test number** 685289815019**Result** ✗ Failed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Front Headlamp aim too low both lamps (4.1.2 (a))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect bulb incorrectly fitted. (4.1.2 (c))**MOT #6** 2020-03-13 11:25**MOT test number** 122183711925**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2019-03-14 16:35**MOT test number** 471911505661**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2017-12-04 17:08**MOT test number** 344460144385**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #3** 2016-11-02 09:48**MOT test number** 300123785847**Result** ✓ Passed**Advice** Engine and underside covers fitted not allowing full inspection**MOT #2** 2016-02-19 13:43**MOT test number** 835834621808**Result** ✓ Passed**MOT #1** 2015-02-23 10:06**MOT test number** 245294855031**Result** ✓ Passed**Notice** Advise inner band of front tyres worn



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 March 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-01
Last registration	2024-03-14
Complete history	See info



Registration #1	2012-03-01	10 mi
Registration #2	2015-02-23	53.468 mi
Registration #3	2016-02-19	69.179 mi
Registration #4	2016-11-02	79.849 mi
Registration #5	2017-12-04	91.450 mi
Registration #6	2019-03-14	98.432 mi
Registration #7	2020-03-13	103.903 mi
Registration #8	2021-03-20	111.277 mi
Registration #9	2022-03-20	118.277 mi
Registration #10	2023-03-20	125.277 mi
Registration #11	2024-03-20	132.277 mi
Registration #12	2025-03-20	139.277 mi
Registration #13	2026-03-20	146.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1574 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1099062