




report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S ECOFLEX
Colour	White
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-06-27
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-28
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	37
Total items failed	16

MOT #17	2023-06-19 11:54
MOT test number	576705595845
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Nail in tyre

**MOT #16**

2023-06-19 11:54

**MOT test number**

239222651828

**Result****✗ Failed**

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #15**

2022-06-29 16:40

**MOT test number**

930238992410

**Result****✓ Passed**

- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Heavily Cracked (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Heavily Cracked (5.2.3 (d) (ii))

**MOT #14**

2022-02-14 15:08

**MOT test number**

886930350419

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #13**

2022-02-14 12:34

**MOT test number**

575391106104

**Result**

✗ Failed

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #12**

2021-02-25 12:13

**MOT test number**

875337994832

**Result**

✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**MOT #11**

2021-02-25 12:13

**MOT test number**

113643455044

**Result****✗ Failed****Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10**

2020-02-27 12:36

**MOT test number**

531213579758

**Result****✓ Passed****MOT #9**

2020-02-27 10:33

**MOT test number**

407078908180

**Result****✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

**MOT #8** 2019-04-20 08:57**MOT test number** 995304832247**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**MOT #7** 2019-04-20 08:57**MOT test number** 264412266166**Result** ✗ Failed**Pass with rectification** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**MOT #6** 2018-04-03 11:39**MOT test number** 911914835713**Result** ✓ Passed**MOT #5** 2017-04-13 09:13**MOT test number** 605256251653**Result** ✓ Passed**MOT #4** 2016-04-18 08:20**MOT test number** 479299971159**Result** ✓ Passed**Advice** Offside Windscreen wiper splitting**Advice** Wear on outer edge of tread on nearside rear Tyre

**MOT #3** 2015-04-20 09:44**MOT test number** 227780715175**Result** ✓ Passed**Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Items removed from driver's view prior to test**MOT #2** 2014-04-23 16:05**MOT test number** 258813814400**Result** ✓ Passed**Notice** Cuts in outer sidewall of nearside rear Tyre**MOT #1** 2014-04-23 11:04**MOT test number** 288753914498**Result** ✗ Failed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Notice** Cuts in outer sidewall of nearside rear Tyre**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
28 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	28 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>GY11USN</b>
Plate since	2015-01-01
Current registration	 <b>GY11USN</b>
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-04-30
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2011-04-30	17 mi
Registration #2	2014-04-23	19.583 mi
Registration #3	2014-04-23	19.586 mi
Registration #4	2015-04-20	24.697 mi
Registration #5	2016-04-18	3.155 mi
Registration #6	2017-04-13	38.877 mi
Registration #7	2018-04-03	44.596 mi
Registration #8	2019-04-20	54.228 mi
Registration #9	2019-04-20	54.228 mi
Registration #10	2020-02-27	57.117 mi
Registration #11	2020-05-20	58.277 mi
Registration #12	2020-05-20	58.277 mi
Registration #13	2020-05-20	58.277 mi
Registration #14	2020-05-20	58.277 mi
Registration #15	2020-05-20	58.277 mi
Registration #16	2020-05-20	58.277 mi
Registration #17	2020-05-20	58.277 mi
Registration #18	2020-05-20	58.277 mi
Registration #19	2020-05-20	58.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	975 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1090505