





report date: 2024-03-28

General information

Make	CITROEN	
Model	BERLINGO MULTISPACE BLUEHDI FEEL	
Colour	Grey	
Year of manufacture	2017	
Top speed	103 mph	
0 - 60 mph	12.4 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	98 BHP	
Max. torque	254 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	55.4 mpg	
Consumption extra urban	72.4 mpg	
Consumption combined	65.7 mpg	
CO2 emission	113 g/km	
CO2 label	С	



CarCheck.co.uk page 1/12



NK17DVO

report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-28

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-18
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	13
Total items failed	2

MOT #9		2024-04-03 11:36
MOT test	number	203458981327
Result		✓ Passed
Next expi	ry date	2025-04-18
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	i))

MOT #8	2023-04-19 08:29
MOT test number	252919108034
Result	✓ Passed

MOT #7	2023-04-19 08:29
MOT test number	500901537091

Result X Failed

Pass with rectification Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6	2022-06-06 09:43
MOT test number	329070393112
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #5 2021-06-07 14:10

MOT test number 881250605250

Result
✓ Passed

MOT #4 2020-12-21 13:11

MOT test number 408290615470

Result

✓ Passed

MOT #3 2020-12-21 13:11

MOT test number 323159497502

Result X Failed

Pass with rectification Stop lamp(s) not working high level brake light inop (4.3.1 (a) (ii))

MOT #2 2019-12-21 11:31

MOT test number 836233062441

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Condition of front blades (smearing)

CarCheck.co.uk page 4/12



MOT #1 2019-12-20 12:50

MOT test number 454024318634

Result X Failed

DANGEROUS Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Condition of front blades (smearing)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

NK17DVO

report date: 2024-03-28

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



NK17DVO

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-03-10
Last registration	2024-04-03
Complete history	See info



Registration #1	2017-03-10	28 mi
Registration #2	2019-12-20	32.269 mi
Registration #3	2019-12-21	32.269 mi
Registration #4	2020-12-21	41.105 mi
Registration #5	2020-12-21	41.105 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		9.777 no

More info >

CarCheck.co.uk page 11/12



NK17DVO

report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	1810 mm
Height	1852 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1374 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHB0026690

CarCheck.co.uk page 12/12