



General information

Make	MINI
Model	MINI (R60) COOPER D ALL4
Colour	Black
Year of manufacture	2011
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-06-08
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	23
Total items failed	7

MOT #17	2023-07-01 08:58
MOT test number	512946587140
Result	✓ Passed
Next expiry date	2024-06-30
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-10-20 06:54
MOT test number	958508307519
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))

MOT #15	2022-10-17 15:22
MOT test number	170287428368
Result	✗ Failed
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #14** 2022-02-14 10:34**MOT test number** 552058630916**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2021-02-17 08:57**MOT test number** 907711486487**Result** ✓ Passed**MOT #12** 2021-02-17 08:56**MOT test number** 468013367327**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #11** 2020-02-13 15:04**MOT test number** 338645411841**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2020-02-13 10:01**MOT test number** 535661044314**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-02-14 10:39**MOT test number** 424070593354**Result** ✓ Passed**MOT #8** 2018-10-27 11:54**MOT test number** 185693722546**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2018-04-25 09:04**MOT test number** 776506666984**Result** ✓ Passed**Advice** Front suspension has slight deterioration of the bonding between metal and flexible material of an upper support bearing BOTH SIDES (2.5.B.3a)**Advice** Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement BOTH REAR (2.4.G.2)**Advice** Wipers smearing slightly**MOT #6** 2017-04-24 14:01**MOT test number** 910633602008**Result** ✓ Passed**Advice** Nearside Front SUSPENSION TOP RUBBER MOUNT SPLITTING**Advice** Rear ANTI ROLL BAR BUSHES ARE WORN**Advice** Offside Front SUSPENSION TOP RUBBER MOUNT SPLITTING

**MOT #5** 2017-04-24 11:51**MOT test number** 371527858596**Result** ✗ Failed**Advice** Offside Front SUSPENSION TOP RUBBER MOUNT SPLITTING**Advice** Nearside Front SUSPENSION TOP RUBBER MOUNT SPLITTING**Advice** Rear ANTI ROLL BAR BUSHES ARE WORN**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #4** 2016-04-28 12:09**MOT test number** 571737731238**Result** ✓ Passed**Advice** Both front shocker tops splitting but not resulting in excessive movment**MOT #3** 2016-04-28 11:28**MOT test number** 598536538857**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Both front shocker tops splitting but not resulting in excessive movment**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2015-05-01 14:35**MOT test number** 156321225166**Result** ✓ Passed**MOT #1** 2014-03-28 13:29**MOT test number** 169907784043**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-30
Last registration	2023-07-01
Complete history	See info



Registration #1	2011-03-30	17 mi
Registration #2	2014-03-28	45.681 mi
Registration #3	2015-05-01	57.856 mi
Registration #4	2016-04-28	69.416 mi
Registration #5	2016-04-28	69.417 mi
Registration #6	2017-04-24	80.662 mi
Registration #7	2017-04-24	80.662 mi
Registration #8	2018-04-25	92.127 mi
Registration #9	2018-10-27	92.803 mi
Registration #10	2019-02-14	92.805 mi
Registration #11	2020-05-01	95.000 mi
Registration #12	2020-05-01	95.000 mi
Registration #13	2020-05-01	95.000 mi
Registration #14	2020-05-01	95.000 mi
Registration #15	2020-05-01	95.000 mi
Registration #16	2020-05-01	95.000 mi
Registration #17	2020-05-01	95.000 mi
Registration #18	2020-05-01	95.000 mi
Registration #19	2020-05-01	95.000 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1380 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	71227743