

Ford



General information

Make	FORD
Model	TRANSIT 290 LIMITED LR P/V
Colour	Silver
Year of manufacture	2014
Top speed	98 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 kW / 155 HP / 123 BHP
Max. torque	350 Nm at 1.450 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	40.9 mpg
CO2 emission	191 g/km
CO2 label	J





MOT history

MOT expiry date	2024-07-02
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	16
Total items failed	1

MOT #8	20	023-07-03 10:01
MOT test	number	254843782074
Result		🗸 Passed
Next expi	ry date	2024-07-02
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Brake pad(s) wearing thin on or close to minimum requirement (1.1.13 (a) (ii))

MOT #7		2023-06-26 09:12
MOT test	number	713357758716
Result		🗙 Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))		e, no longer prevents
MAJOR	Offside Steering rack gaiter missing or no longer prevents the ingress of d	irt split (2.1.3 (g) (ii))
Advice	Front Brake pad(s) wearing thin on or close to minimum requirement (1.1.	13 (a) (ii))



МОТ #6	2022-02-25 13:35
MOT test number	817387531544
Result	✓ Passed
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in errear pin or bush (5.3.4 (a) (i))	excessive movement
Advice Offside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii))	
Advice Offside Steering rack gaiter: severely deteriorated	
Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteri	orated (5.3.4 (b) (i))

MOT #5	2022-02-25 13:35
MOT test number	582693966295
Result	🗙 Failed
Pass with rectification Nearside Rear Tyre has a cut in excess of the requireach the ply or cords (5.2.3 (d) (i))	irements deep enough to
Advice Offside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii))	
Advice Offside Steering rack gaiter: severely deteriorated	
Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulti rear pin or bush (5.3.4 (a) (i))	ng in excessive movement

MOT #4	2020-12-03 09:29
MOT test number	559529154753
Result	✓ Passed
Advice Rear Cracks in tyre treads both rear. Ok for now.	

MOT #3	2019-12-13 10:38
MOT test number	892886044360
Result	✓ Passed



CE64DHP
report date: 2024-03-28

MOT #2	2018-12-10 09:46
MOT test number	873816818611
Result	✓ Passed
MOT #1	2017-09-23 08:35
MOT test number	417843227806
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 July 2024	✓ MOT Expires: 2 July 2024
Tax status	Valid until 1 July
Days left	64
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-09-18
Last registration	2023-07-03
Complete history	See info



Registration #1	2014-09-18	11 mi
Registration #2	2017-09-23	46.250 mi
Registration #3	2018-12-10	61.825 mi
Registration #4	2019-12-13	68.534 mi
Registration #5	2020-12-03	73.483 mi
Registration #6		11.177 esi
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight	
Width	2290 mm
Height	1976 mm
Length	5339 mm
Wheel base	3300 mm
Kerb weight	1886 kg
Max. allowed weight	2900 kg
Additional information	
Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of seats	3
Number of axles CarCheck.co.uk	2 page 11/11