





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GTE ADVANCE DSG
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.6 seconds
0 - 60 mph	7.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	115 kW / 157 HP / 215 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.395 сс
Cylinders	4
Fuel type	Llubrid / Floatric
i dei type	Hybrid / Electric
Consumption combined	166.2 mpg
71	•



CarCheck.co.uk page 1/11



VX18KVK

report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-29

Pictures 27

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-27
Pictures	28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-19
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #5	2023-09-11 11:00
MOT test number	266260472380
Result	✓ Passed
Next expiry date	2024-09-19

MOT #4	2022-09-01 10:16
MOT test number	125831535298
Result	✓ Passed

MOT #3	2021-09-20 12:37
MOT test number	708908479385
Result	✓ Passed

MOT #2	2021-02-25 09:57

MOT test number 362454275934

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn close to legal limit and wearing on inner edge (5.2.3 (e))

CarCheck.co.uk page 3/11



MOT #1 2021-02-24 15:23

MOT test number 168045802015

Result

× Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn close to legal limit and worn on inner edge (5.2.3 (e))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Light perishing/cracks (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn close to legal limit and worn on inner edge (5.2.3 (e))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Nail in tyre

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn close to legal limit and worn on both edges (5.2.3 (e))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Light perishing/cracks (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check





Expires: 19 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SIPE
Plate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-05
Last registration	2023-09-11
Complete history	See info



Registration #1	2018-03-05	21 mi
Registration #2	2021-02-24	35.661 mi
Registration #3	2021-02-25	35.661 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1660 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CUKC118668