





report date: 2024-03-28

## General information

Make	VOLVO
Model	S60 D3 BUSINESS EDITION
Colour	Grey
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/11



# Internet history


## Entry 1

Date 2021-07-04

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2023-10-16
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	4
Total items failed	3

MOT #8	2022-10-10 09:02
MOT test number	569857299075
Result	✓ Passed
Next expiry date	2023-10-16
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely	y deteriorated (6.1.7 (g) (i))

MOT #7	2021-10-17 15:06
MOT test number	832139581925
Result	<b>✓</b> Passed

MOT #6	2021-04-19 16:37
MOT test number	804123814074
Result	<b>✓</b> Passed

MOT #5	2021-04-19 16:37
MOT test number	532605892293
Result	<b>▼</b> Failed
Pass with rectification all lamps (4.7.1 (b) (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or
Pass with rectification	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or
all lamps (4.7.1 (b) (ii))	

CarCheck.co.uk page 3/11



**DANGEROUS** 

YY66ANF report date: 2024-03-28

MOT #4 2020-10-21 08:24 **MOT test number** 279083972616 Result ✓ Passed MOT #3 2020-10-14 15:00 **MOT test number** 377026133075 Result × Failed Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

 MOT #2
 2019-09-18 14:54

 MOT test number
 711616874494

 Result
 ✓ Passed

 MOT #1
 2019-09-18 14:54

 MOT test number
 250157938251

 Result
 X Failed

 Pass with rectification
 Offside Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 4/11



#### Tax & MOT check



X MOT

Tax expired: 1 March 2023

Expired: 16 October 2023

Tax status	Expired at 1 March 2023
Days left	424 days too late
MOT expiry date	16 October 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



## Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



$\sim$		100	
Owi	ner	nıs	torv

e when mistery	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full research	
MARKET STATE OF THE STATE OF TH	
***************************************	
***************************************	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 8/11



## Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-05
Last registration	2022-10-10
Complete history	See info



Registration #1	2016-10-05	8 mi
Registration #2	2019-09-18	61.702 mi
Registration #3	2019-09-18	61.702 mi
Registration #4	2020-10-14	79.902 mi
Registration #5	2020-10-21	79.904 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.377 es

More info >

CarCheck.co.uk page 10/11



Car features

The VOLVO factory car options list is only available in the premium report.		
S0225	Air conditioning	
S0295		
S0482		
S0501		
S0566		
S0567		
S0569		

Safety ratings

NCAP rating

Video

see crash video

View the complete VOLVO factory list for this vehicle <u>here</u>.



More info >

# Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1580 kg
Max. allowed weight	2090 kg

## Additional information

Fuel tank capacity	67	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pa	age 11/11

Number of axles 2

Engine number 1798437